This is a digital copy of a book that was preserved for generations on library shelves before it was carefully scanned by Google as part of a project to make the world's books discoverable online.

It has survived long enough for the copyright to expire and the book to enter the public domain. A public domain book is one that was never subject to copyright or whose legal copyright term has expired. Whether a book is in the public domain may vary country to country. Public domain books are our gateways to the past, representing a wealth of history, culture and knowledge that's often difficult to discover.

Marks, notations and other marginalia present in the original volume will appear in this file - a reminder of this book's long journey from the publisher to a library and finally to you.

Usage guidelines

Google is proud to partner with libraries to digitize public domain materials and make them widely accessible. Public domain books belong to the public and we are merely their custodians. Nevertheless, this work is expensive, so in order to keep providing this resource, we have taken steps to prevent abuse by commercial parties, including placing technical restrictions on automated querying.

We also ask that you:

+ *Make non-commercial use of the files* We designed Google Book Search for use by individuals, and we request that you use these files for personal, non-commercial purposes.
+ *Refrain from automated querying* Do not send automated queries of any sort to Google's system: If you are conducting research on machine translation, optical character recognition or other areas where access to a large amount of text is helpful, please contact us. We encourage the use of public domain materials for these purposes and may be able to help.
+ *Maintain attribution* The Google "watermark" you see on each file is essential for informing people about this project and helping them find additional materials through Google Book Search. Please do not remove it.
+ *Keep it legal* Whatever your use, remember that you are responsible for ensuring that what you are doing is legal. Do not assume that just because we believe a book is in the public domain for users in the United States, that the work is also in the public domain for users in other countries. Whether a book is still in copyright varies from country to country, and we can't offer guidance on whether any specific use of any specific book is allowed. Please do not assume that a book's appearance in Google Book Search means it can be used in any manner anywhere in the world. Copyright infringement liability can be quite severe.

About Google Book Search

Google's mission is to organize the world's information and to make it universally accessible and useful. Google Book Search helps readers discover the world's books while helping authors and publishers reach new audiences. You can search through the full text of this book on the web at `http://books.google.com/`

1817
ARTES VERITAS SCIENTIA
LIBRARY OF THE
UNIVERSITY OF MICHIGAN
E PLURIBUS UNUM
TUEBOR
SI QUAERIS PENINSULAM AMOENAM
CIRCUMSPICE

THE GIFT OF
Jean M. E. Cooley

Digitized by Google

No. 19.—STRENGTH OF BEAMS UNDER TRANSVERSE LOADS. By Prof. W. Allan, author of "Theory of Arches." Second edition, revised.

No. 20.—BRIDGE AND TUNNEL CENTRES. By John B. McMaster, C.E. Second edition.

No. 21.—SAFETY VALVES. Second Edition. By Richard H. Buel, C.E.

No. 22.—HIGH MASONRY DAMS. By E. Sherman Gould, M. Am. Soc. C. E.

No. 23.—THE FATIGUE OF METALS UNDER REPEATED STRAINS. With various Tables of Results and Experiments. From the German of Prof. Ludwig Spangenburgh, with a Preface by S. H. Shreve, A.M.

No. 24.—A PRACTICAL TREATISE ON THE TEETH OF WHEELS. By Prof. S. W. Robinson. Second edition, revised.

No. 25.—ON THE THEORY AND CALCULATION OF CONTINUOUS BRIDGES. By R. M. Wilcox, Ph. D.

No. 26.—PRACTICAL TREATISE ON THE PROPERTIES OF CONTINUOUS BRIDGES. By Charles Bender, C.E.

No. 27.—ON BOILER INCRUSTATION AND CORROSION. By F. J. Rowan. New Ed. Rev. by F. E. Idell.

No. 28.—TRANSMISSION OF POWER BY WIRE ROPES. Second edition. By Albert W. Stahl, U.S.N.

No. 29.—STEAM INJECTORS. Translated from the French of M. Leon Pochet.

No. 30.—TERRESTRIAL MAGNETISM AND THE MAGNETISM OF IRON VESSELS. By Prof. Fairman Rogers.

No. 31.—THE SANITARY CONDITION OF DWELLING-HOUSES IN TOWN AND COUNTRY. By George E. Waring, jun.

No. 32.—CABLE-MAKING FOR SUSPENSION BRIDGES. By W. Hildebrand, C.E.

No. 33.—MECHANICS OF VENTILATION. By George W. Rafter, C.E. New and Revised Edition.

No. 34.—FOUNDATIONS. By Prof. Jules Gaudard, C.E. Second edition. Translated from the French.

No. 35.—THE ANEROID BAROMETER: ITS CONSTRUCTION AND USE. Compiled by George W. Plympton. Eighth edition.

No. 36.—MATTER AND MOTION. By J. Clerk Maxwell, M.A. Second American edition.

No. 37.—GEOGRAPHICAL SURVEYING: ITS USES, METHODS, AND RESULTS. By Frank De Yeaux Carpenter, C.E.

No. 38.—MAXIMUM STRESSES IN FRAMED BRIDGES. By Prof. William Cain, A.M., C.E. New and revised edition.

Digitized by Google

No. 39.—A HANDBOOK OF THE ELECTRO-MAGNETIC TELEGRAPH. By A. E. Loring.

No. 40.—TRANSMISSION OF POWER BY COMPRESSED AIR. By Robert Zahner, M.E. Second edition.

No. 41.—STRENGTH OF MATERIALS. By William Kent, C. E., Assoc. Editor, *Engineering News*. Second Ed.

No. 42.—THEORY OF STEEL-CONCRETE ARCHES, AND OF VAULTED STRUCTURES. By Prof. William Cain.

No. 43.—WAVE AND VORTEX MOTION. By Dr. Thomas Craig, of Johns Hopkins University.

No. 44.—TURBINE WHEELS. By Prof. W. P. Trowbridge, Columbia College. Second edition. Revised.

No. 45.—THERMODYNAMICS. By Prof. H. T. Eddy, University of Cincinnati.

No. 46.—ICE-MAKING MACHINES. From the French of M. Le Doux. Revised by Prof. Denton.

No. 47.—LINKAGES; THE DIFFERENT FORMS AND USES OF ARTICULATED LINKS. By J. D. C. de Roos.

No. 48.—THEORY OF SOLID AND BRACED ARCHES By William Cain, C.E.

No. 49.—ON THE MOTION OF A SOLID IN A FLUID. By Thomas Craig, Ph.D.

No. 50.—DWELLING-HOUSES: THEIR SANITARY CONSTRUCTION AND ARRANGEMENTS. By Prof. W. H. Corfield.

No. 51.—THE TELESCOPE: ITS CONSTRUCTION, ETC. By Thomas Nolan.

No. 52.—IMAGINARY QUANTITIES. Translated from the French of M. Argand. By Prof. Hardy.

No. 53.—INDUCTION COILS: HOW MADE AND HOW USED. Fifth edition.

No. 54.—KINEMATICS OF MACHINERY. By Prof. Kennedy. With an introduction by Prof. R. H. Thurston.

No. 55.—SEWER GASES: THEIR NATURE AND ORIGIN. By A. de Varona. 2d ed., revised and enlarged.

No. 56.—THE ACTUAL LATERAL PRESSURE OF EARTHWORK. By Benjamin Baker, M. Inst. C.E.

No. 57.—INCANDESCENT ELECTRIC LIGHTING. A Practical Description of the Edison System. By L. H. Latimer, to which is added the Design and Operation of Incandescent Stations. By C. J. Field, and the Maximum Efficiency of Incandescent Lamps, by John W. Howell.

No. 58.—THE VENTILATION OF COAL-MINES. By W. Fairley, M.E., F.S.S., and Geo. J. André.

No. 59.—RAILROAD ECONOMICS; OR, NOTES, WITH COMMENTS. By S. W. Robinson, C.E.

Digitized by Google

E. L. C.
March 1906

Worm and Spiral Gearing

TJ
200
.H196

BY

FREDERICK A. HALSEY,
ASSOCIATE EDITOR "AMERICAN MACHINIST."

REPRINTED FROM
"AMERICAN MACHINIST."

NEW YORK:
D. VAN NOSTRAND COMPANY.
23 MURRAY AND 27 WARREN STREETS.
1902.

Digitized by Google

COPYRIGHT, 1902, BY D. VAN NOSTRAND CO.

Digitized by Google

Gift
Dean M.E. Cooley
7-2-31

PREFACE.

JUSTIFICATION for the republication of the contents of this book is found in the still prevalent opinion among designers of machinery that worm gearing is necessarily short lived and of low efficiency, and in the fact that the methods of laying out spiral gearing are not as widely understood as the merit and convenience of that form of gearing make desirable.

The theory of worm gearing is well fortified by the collection of facts from experience given herein, and it points out clearly the procedure to be followed in order to insure durability and efficiency. Both analytical and graphical methods of laying out spiral gearing are given, and these, it is believed, will meet the needs and tastes of all.

Digitized by Google

1903

Digitized by Google

CONTENTS.

PART I.

WORM GEARING.

PAGE

Worm Gearing..... 9
Theory of Worm Efficiency..... 11
Experimental Corroboration of the Theory.. 18
Examples from Practice..... 24
Limiting Speed and Pressure..... 36
Step Bearings..... 40

PART II.

SPIRAL GEARING.

Spiral Gears compared with Spur Gears.—
The different Pitches..... 44
The Speed Ratio..... 51
The Preliminary Solution..... 57
The Lengths of the Normal Helixes..... 60
A Practical Example..... 62
Final Solution by changing the Center Distance..... 65

Digitized by Google

PAGE
Graphical Solution with changed Center Distance 67
Final Solution with unchanged Center Distance..... 69
Graphical Solution with unchanged Center Distance..... 74
Finding the Pitch of the Tooth Helix..... 76
Special Solution for a Helix Angle of 45 Degrees 77
Graphical Solution for a Helix Angle of 45 Degrees..... 81
The Selection of the Cutter..... 83

Digitized by Google

ILLUSTRATIONS.

The illustrations are too large to go in the text where they belong, and, with two exceptions noted below, will be found, folded, at the end of the book.

FIGURE PAGE.

1.—The Principle of Worm Efficiency,... 12

2.—Relation between Thread Angle and Efficiency.

3.—Relation between Thread Angle, Speed, and Efficiency, with Cases from Practice.

4.—Hewes & Phillips' Unsuccessful Worm.

5.—Hewes & Phillips' Successful Worm.

6.—The Newton Worm and Step.

7.—The Bertram Worm.

8 to 11.—Tooth and Normal Helixes with their Development.

12 to 15.—The Speed Ratio.

16.—A Pair of Gears Developed.

17.—Adjusting the Diameters when the Center Distance can be Changed.

Digitized by Google

FIGURE PAGE

18.—Graphical Solution with Variable Center Distance.

19.—Adjusting the Diameters when the Center Distance is Fixed.

20.—Graphical Solution with Fixed Center Distance.

21.—Finding the Pitch of the Tooth Helix. 90

22.—Relation of Normal Helix and Diameter in Spiral Gears having a Tooth Angle of 45 Degrees.

23.—Simple Graphical Solution for Spiral Gears having a Tooth Angle of 45 Degrees.

Digitized by Google

PART I.

WORM GEARING.

In view of the good results now being obtained with worm gearing, the old prejudice against that form of gearing, on account of its supposed low efficiency and short life, is dying out. These good results are the outcome of the application of principles which are by no means a late discovery, and it is expected that what follows will contain much that to some readers is not new. At the same time it is an undoubted fact that the best practice with worms is understood by but few, relatively speaking, and the corroboration of the theory by examples from practice which follow, is believed to be new. No better illustration of the fact that good practice with worm gearing is not

Digitized by Google

yet widely understood could be given than the statement in a recent and excellent work on gearing that "the diameter of the worm is commonly made equal to four or five times the circular pitch," the fact being that such proportions are distinctly bad if the worm is to do hard work.

It should be stated at the beginning that while what follows is not offered as a presentation of all the data necessary for assured success with worms under all conditions, it is hoped to make the general conditions of successful practice plain, and to present the "state of the art" as it exists to-day.

The essential change in practice which has improved the results obtained with worm gearing has been an increase in the pitch angle over what was formerly considered proper. There is no doubt whatever that this change has increased the efficiency of the gear, and, what is of more importance, has reduced the tendency to heat and rapid wear. This is

Digitized by Google

not only a fact, but it is a sound conclusion from theoretical considerations, which might have been predicted under proper examination.

THEORY OF WORM EFFICIENCY.

The reason why an increase of pitch, other things being equal, or in other words, an increase of the angle of the thread, gives these results, will be understood from Fig. 1. If *a b* be the axis of the worm and *c d* a line representing a thread, against which a tooth of the wheel bears, it will be seen that if the tooth bears upon the thread by a pressure *P*, that pressure may be resolved into two components, one of which, *e f*, is perpendicular, while the other, *e g*, is parallel to the thread surface. The perpendicular component produces friction between the tooth and the thread. The useful work done during a revolution of the thread is the product of the load *P* and the pitch of the worm, while the work lost in friction is the product of the perpendicular pres-

Digitized by Google

sure $e\,f$, the coefficient of friction and the distance traversed in a revolution, which is the length of one turn of the thread. Now, if the angle of the thread be doubled, as indicated, the load P remain-



Fig. 1. THE PRINCIPLE OF WORM EFFICIENCY.

ing the same, the new perpendicular component $f\,h$ of P will be slightly reduced from the old value $e\,f$, while the length of a turn of the thread will be slightly increased. Consequently their product and the lost work of friction per revolution

Digitized by Google

will not be much changed. The useful work per revolution will, however, be doubled, because, the pitch being doubled, the distance traveled by P in one revolution will be doubled. For a given amount of useful work the amount of work lost is therefore reduced by the increase in the thread angle, and, since the tendency to heat and wear is the immediate result of the lost work, it follows that that tendency is reduced. For small angles of thread the change is very rapid, and continues, though in diminishing degree, until the angle reaches a value not far from 45 degrees, when the conditions change and the lost work increases faster than the useful work, an increase of the angle of the thread beyond that point reducing the efficiency.

This general consideration of the subject shows the principles at the bottom of successful worm design, but a more exact examination is desirable. According to Professor Barr the efficiency of a

Digitized by Google

worm gear, the friction of the step being neglected, is :

$$e = \frac{\tan \alpha \, (1 - f \tan \alpha)}{\tan \alpha + f}$$

in which

e = efficiency,

α = angle of thread, being the angle $d\,f\,i$ of Fig. 1,

f = coefficient of friction.

To study the effect of the step, a convenient assumption is that the mean friction radius of the step is equal to that of the worm. This assumption would only be realized in cases where the step is a collar bearing outside the worm shaft, and the preceding and following formulas therefore represent extreme cases, one of a frictionless step, which would be approximated by a ball bearing, and the other of a step having about the extreme friction to be met with. Most actual cases would therefore fall between the two. Again, according to Professor

Digitized by Google

Barr, the efficiency of a worm and step on the above assumption is : *

$$e = \frac{\tan \alpha (1 - f \tan \alpha)}{\tan \alpha + 2f} \text{ (approximately)}$$

Notation as before.

These formulas give no clear indication of the manner in which the efficiency varies with the angle, and the diagram, Fig. 2, has been constructed to show this to the eye. The scale at the bottom gives the angles of the thread from 0 to 90 degrees, while the vertical scale gives the calculated efficiencies, the values of which have been obtained from the equations and plotted on the diagram. The upper curve is from the first equation, and gives the efficiencies of the worm thread only; while the lower curve, from the second equation, gives the combined efficiency of the worm and step. In the

* In Professor Barr's formulas it is assumed that the worm thread is square in section. Thread profiles in common use affect the results but little.

Digitized by Google

calculations for the diagram it is necessary to assume a value for f, and this has been taken at .05, which is probably a fair mean value. The experiments made by Mr. Wilfred Lewis for Wm. Sellers & Co. showed an increase of efficiency with the speed. The present diagram may be considered as confined to a single speed, and at the same time is not to be understood as showing the exact efficiency to be expected from worms, but rather to exhibit to the eye the general law connecting the angle of the thread with the efficiency.

The curves will be seen to rise to a maximum and then to drop. The exact values of the angle of thread to give maximum efficiency may be easily found by the methods of the calculus, the results being:

For worm thread alone the efficiency is at a maximum when

$$\tan \alpha = \sqrt{1 + f^2} - f.$$

Substituting the value of f (.05) used in calculating the diagram, this becomes

Digitized by Google

$\tan \alpha$ for maximum efficiency $= .9512$,

and by referring to a table of natural tangents we find that

α for maximum efficiency $= 43° \; 34$.

Similarly for the worm and step the result is

$\tan \alpha$ for maximum efficiency $=$ $\sqrt{2 + 4 f^2} - 2 f$, which for $f = .05$ $= 1.318$,

and a table of tangents tells us again that

α for maximum efficiency $= 52° \; 49'$.

Of more importance than the angle of maximum efficiency is the general character of the curves, of which the most pronounced peculiarity is the extreme flatness, showing that for a wide range of angles the efficiency varies but little. Thus, for the upper curve there is scarcely any choice between 30 and 60 degrees of angle, and but little drop at 20 degrees.

At first sight the lower curve might be

Digitized by Google

thought the most useful of the two, as it includes the effect of the step, but a little consideration will show that this is not the case. For most cases in which worms are used the efficiency of the transmission, as such, is of very little account. What the designer concerns himself with is the question of durability and satisfactory working, and the results to be expected in this respect are best shown by the upper curve, in which high efficiency means a durable worm. Throughout this discussion, in fact, the chief significance of efficiency lies in the fact that low efficiency means rapid wear and vice versa.

EXPERIMENTAL CORROBORATION OF THE THEORY.

The experiments of Wm. Sellers & Co., before referred to, go far to confirm the soundness of the above views. From the present standpoint it is unfortunate that those experiments did not cover a wider range of worm thread angles—those act-

Digitized by Google

ually used being 5 degrees, 7 degrees, and 10 degrees. Other experiments were, however, made on spiral pinions of higher angles, spiral pinions being understood by Mr. Lewis to mean those pinions having the mating gear a true spur, the pinion shaft being at a suitable angle with the gear shaft to bring the pinion in proper mesh—a construction which is exemplified in the well-known Sellers planer drive. Mr. Lewis gives a formula by which the efficiencies of worms can be calculated from those for spiral pinions, and in the absence of direct experiments on worms of high angles, his results for spiral pinions have been modified by this formula to read for worms. The results for the two forms of gearing differ by less than five per cent. for the extreme case of his experiments. To compare the results obtained by Mr. Lewis with Professor Barr's formula, a speed has been selected from the experiments giving the nearest coefficient of friction to that used in obtaining the curves of Fig. 2. The

Digitized by Google

results have been plotted in Fig. 2, where they appear as small crosses, and will be seen to have a very satisfactory agreement with the lower curve, with which they should be compared, as the steps of the worms used by Mr. Lewis were of the usual pattern without balls.

The variation of the coefficient of friction with the speed lends an interest to Fig. 3, which is a series of curves obtained from the results published by Mr. Lewis in the same manner as the crosses of Fig 2, the curve for 20 feet velocity being in fact the same as that appearing as crosses in Fig. 2. The other curves of Fig. 3 are obtained from those of Mr. Lewis, and cover a range of velocities from 3 to 200 feet per minute at the pitch line, as noted at the right. In this diagram the results obtained by Mr. Lewis on worms are plotted direct, but the experiments on spiral pinions have been modified as explained above. Inspection of the curves shows that while there is a progressive increase of efficiency with the

Digitized by Google

speed, there is, nevertheless, not much probability, or indeed room, for further improvement beyond the speed of 200 feet per minute. It will furthermore be seen that the efficiency drops off much less for low angles of thread at high speeds than at low.

In interpreting this diagram, it should be remembered that the durability of a worm depends upon the amount of power lost in wear, and not upon the percentage so lost. The ability of a given worm to absorb and carry off the heat due to friction is fixed, and does not vary with the speed. That is, a given worm running at 100 revolutions under a given pressure can carry off as much friction heat as the same worm at 200 revolutions, while it, under the same pressure would transmit but one-half the power in the former case that it would in the latter. In other words, the percentage of lost work might be twice as much at the lower speed as at the higher without increasing the tendency to heat.

Digitized by Google

The increase of efficiency with the speed is a valuable property of worms, and enables them to do much more work than they otherwise would. Thus the 20 degree worm at 20 feet per minute lost 21½ per cent. of the work in friction. Increasing the speed to 40 feet doubled the work applied, and, had the efficiency remained constant, would have doubled the friction heat to be dissipated. In point of fact, this increase of speed diminished the percentage of loss to 17, and the amount of loss and heat, instead of being doubled, was only increased in the ratio of 160 to 100. It is plain from the diagram, however, that this action does not continue much beyond a velocity of 200 feet per minute, beyond which the amount of loss must be more nearly proportional to the speed, and this doubtless has some connection with the fact observed by Mr. Lewis that 300 feet per minute is the limit of speed when the gears are loaded to their working strength, and that the best conditions are obtained at

Digitized by Google

about 200 feet per minute. It is proper to add, however, that in the cases from practice given later there are three which have been made repeatedly, and which are conspicuously successful, in which the velocity exceeds 600 feet, and one in which it exceeds 800 feet. No doubt, in all such cases, if the pressure on the teeth could be known it would be found to be light.

It will be seen that an increase of speed for any worm under constant pressure leads to an increase of friction work, and the limit is reached when the worm is no longer able to carry off the heat generated fast enough to prevent undue rise in temperature. Furthermore, this limiting speed depends upon the pressure, it being higher for low pressures than for high. A worm having an angle which might be successful at low speed may fail at high speed; but it would seem that any worm which is successful at high speed should also be successful at low, which is in accordance with mechanical instinct.

Digitized by Google

There are, it will be observed, two methods of increasing the pitch angle. The diameter may be kept constant and the pitch be increased, or the pitch may be kept constant and the diameter be reduced. From a mathematical standpoint, these two methods are identical; that is, at a given pitch line velocity a worm of a given angle should have the same efficiency, regardless of the diameter; but in a mechanical sense the methods are not identical. The worm of the larger diameter would naturally have a gear of wider face and the pair, having greater area of tooth surface in contact would carry a larger load.

EXAMPLES FROM PRACTICE.

It is impossible to say who was the first to recognize the significance of the pitch angle as a factor in the satisfactory performance of worm gearing, but it may be mentioned as a matter of interest that the exhibit of the Hewes & Phillips Iron Works at the Newark Industrial Exhibi-

Digitized by Google

tion of 1873 included several worm-driven planers, in which the worms were double threaded and had a pitch angle of 15° 15′, a pitch diameter of 3½ inches, a pitch of 3 inches, and a speed, cutting, of 256 and backing of 640 r. p. m., which give pitch line velocities of 237 and 590 feet. This worm was successful, and was many times repeated; but later on Hewes & Phillips were struck by the high belt speed idea, and in order to increase the belt speed they changed the worm to 6.16 p. d., 1¾ inches pitch, single thread; speed, cutting, 446, and backing 1,110 r. p. m., giving a pitch angle of 5° 15′ and pitch line velocities of 720 and 1780 feet. This worm was a failure, and was soon changed to 6.16 p. d., 3½ inches pitch, double thread; speed, cutting, 281, and backing 700 r. p. m., giving an angle of 10° 15′ and pitch line velocities of 452 and 1,130 feet. This worm did better than the last, but not so well as the first. By this time the lesson was learned, and Hewes & Phillips set out to use a worm

Digitized by Google

of 30 degrees pitch angle. Structural considerations, however, prevented the use of so high an angle and they compromised on 20 degrees, the final worm resulting from this experience having a pitch diameter of 2.63 inches, with 3 inches pitch, quadruple thread, the speed cutting being 300 and backing 700 r. p. m., giving pitch line velocities of 205 and 480 feet, and this remained the standard angle as long as these planers were manufactured. The writer has seen one of these 20 degree worm gears, opened up after twelve years' use, and the wear disclosed was very slight—no shoulder being in existence. As a result of the experience outlined above, this house adopted the standard practice of making the worms as small as possible in diameter, and giving the threads in all cases a pitch angle of 20 degrees. The form of tooth used was the epicycloidal, while the materials used were hard cast-iron for the gear and case-hardened open-hearth steel for the worms.

Digitized by Google

These Hewes & Phillips worms are plotted in Fig. 3 as crosses 1, 2, 3, 4, of which 1 is the 15° 15′, 2 the 5° 15′, 3 the 10° 15′, and 4 the 20°, the first and last being successes, and the second and third failures.

In plotting these worms, and all others having pitch line velocities above 200 feet, the crosses are placed near and above the 200 feet curve. It is unfortunate that we have no curves for higher speeds, but Mr. Lewis recommends the use of the 200 feet line for all higher speeds. Leaders connecting different crosses indicate the same worm at different speeds in all cases. The letters *s* and *f* on the diagram mean success or failure in all cases.

Fig. 4 is a drawing of worm 3 (failure) and Fig. 5 shows worm 4 (success), and no more instructive pair of drawings could be imagined than these. The pitches are not far different, and what difference there is is in favor of the larger worm. The duty is the same, the gears are of about the same diameter, and

Digitized by Google

the revolutions per minute are nearly the same. The essential change is in the increase of the pitch angle by a reduction of the diameter, and this changed failure to success.

The Newton Machine Tool Works use worm gearing in many of their machines, notably their cold saw cutting-off machines. In the earlier machines of this class the worm had a pitch diameter of $2\frac{7}{8}$ inches, with a pitch of 1 inch, single thread, the revolutions per minute being 765. These figures give a pitch angle of 6° 20′, and a pitch line velocity of 572 feet. This machine could be operated, but not with satisfaction on account of the heating and short life of the worm. The worm was then increased in pitch by making it double threaded, giving a pitch angle of 12° 30′, the speed being reduced to 500 revolutions per minute, giving a pitch line velocity of 375 feet. The change proved to be a great improvement, heavier work than was before possible being done after the change without

Digitized by Google

distress or difficulty, and this worm has since been applied to a large number of machines with entire success. A still later worm used on these machines has a pitch diameter of $3\frac{7}{8}$ inches and a pitch of 4 inches. triple threads, giving a pitch angle of 18° 15′, and this is found to be a still further improvement. This last worm is used on a wide variety of machines and at a variety of speeds from 40 to 680 r. p. m., giving pitch line velocities of from 40 to 685 feet, and with uniformly good results. In many cases it is used without an oil cellar, though for comparatively light work. The form of thread used is the involute, and the material is hardened steel for the worm and bronze for the wheel. These Newton worms appear in Fig. 3 as 5, 6, 7, of which 5 is nearly a failure, while 6 and 7 are entirely successful. The second Newton worm—the one appearing in Fig. 3 as 6—is shown in Fig. 6.

Another habitual user of worms is John Bertram & Sons, of Dundas, Ontario, Can-

Digitized by Google

ada, who employ them in all their planers, and use largely a worm of 3.18 inches pitch diameter, 4 inches pitch, quadruple threads, the speed, cutting, being 186 and reversing 744 r. p. m. These figures give a pitch angle of 22 degrees, and pitch line velocities of 155 and 620 feet. This worm appears in Fig. 3 as 8, the vertical position for the higher speed being again uncertain. These worms are highly successful, as the writer knows from repeated observation. Both worm and wheel are of cast-iron, the thread being Brown & Sharpe standard. The Bertram worm is shown in Fig. 7. In reading this drawing it should be remembered that the conventional representation of a worm, with the threads shown by straight lines, shows a larger apparent pitch angle than the true one, as shown by a true projection.

Another case of failure was a worm drive applied to a large boring machine, the worm being 12 inches pitch diameter, 8 inches pitch, quadruple thread, speed

Digitized by Google

80 r. p. m. and above, worm of forged steel, wheel of bronze, oil cellar lubrication. These figures give a pitch angle of 12 degrees and a pitch line velocity of 250 feet. This worm is located on Fig. 3 as 9.

Still other cases of change from failure to success are supplied by Mr. Jas. Christie, of the Pencoyd Iron Works. The first of these relates to a boring machine, which was, by the makers, supplied with a worm drive having a worm of $5\frac{1}{2}$ inches pitch diameter, $1\frac{1}{2}$ inches pitch, single thread, steel worm and cast-iron wheel, average speed 150 r. p. m. These figures give a pitch angle of 5 degrees and a pitch line velocity of 215 feet. This was a failure, but was successfully replaced by a worm of $4\frac{7}{8}$ inches pitch diameter, $2\frac{1}{2}$ inches pitch, and the same number of revolutions, which figures give a pitch angle of 9° 15′ and a pitch line speed of 190 feet. These two worms appear as 10 and 11. This successful worm lies in the region of unsuccessful ones, but the in-

Digitized by Google

fluence of the increased lead angle is unmistakable. The fact of its success is probably due to the pressure on the teeth being well below the working strength, or to the speed being moderate, or both.

The second case, of which the data were supplied by Mr. Christie, relates to two heavy milling machines, in which the cutter spindles were driven by worms 6 inches pitch diameter by 1½ inches pitch, single thread. It was found that the cutters could be run much faster than was originally contemplated, and the worms were consequently speeded up to about 500 r. p. m. In these machines cast-iron worm wheels were speedily destroyed, while hardened steel worms and bronze wheels would last about a year. Later two more machines were built having steel worms and bronze wheels, the worms being 4½ inches pitch diameter by 5 inches pitch, quadruple threads, speed 280 r. p. m. These worms have been in use six years, and are described as being "good as new." The data given for the first

Digitized by Google

worm give a pitch angle of 4° 30′ and a pitch line velocity of 785 feet. It appears in Fig. 3 as 12. The pitch angle of the second worm is 19° 30′, and its pitch line velocity 328 feet. It appears in Fig. 3 as 13.

Mr. Christie has made many successful changes, of which these are typical, and he now uses worms with great freedom and success. His general conclusion is that good worms begin with those having the pitch about equal to the diameter, giving a pitch angle of 17° 15′.

Another equally striking case of success accompanying an increase of the pitch angle is supplied by Mr. W. P. Hunt, of Moline, Ill., who says :

"In building a special double-spindle lathe I wished to use a worm drive, and having a single-thread ¾-inch pitch hob, 2¾-inch outside diameter, I decided to work to that, and made my gear with twenty-six teeth, giving a speed reduction of 26 to 1. The worm was to ruu at 460 revolutions per minute, but upon starting

Digitized by Google

the machine I found it impossible to keep the worm and gear cool, and the belts would not pull the cut.

"Accordingly I decided to make a new worm and hob having the same outside diameter as the one first tried, but with double thread and 2-inch pitch, and a new gear having forty-eight teeth, giving me a speed reduction of 24 to 1, or less than at first.

"Upon starting the machine with the new worm and gear, not only did it run perfectly cool, but the belts have ample power. We use graphite and oil on the worm, and it is not enclosed."

Mr. Hunt does not give the pitch diameter of his worms, but assuming the threads to have been in accordance with the Acme standard, the pitch diameters are $2\frac{3}{8}$ and $2\frac{1}{4}$ inches respectively, the thread angles being 5° 44′ and 15° 48′, and the pitch line speeds 286 and 271 feet per minute. Mr. Hunt's worms are plotted in Fig. 3 as 17 and 18.

Three other cases of successful worms

Digitized by Google

under heavy duty are found in milling machines which have been repeated many times. The first two worms would ordinarily be described as spiral gears. The shafts are at right angles and the action is that of worms, and they are properly included here.

The first of these, which appears as 14 in the diagram, has a pitch diameter of 2¼ inches, a pitch angle of 45°, and a speed varying between 180 and 945 r. p. m., giving pitch line velocities of 106 to 555 feet per minute. Both gears are of cast-iron. The second, 15 in the diagram, is of the same style, and has the same pitch diameter, with speeds varying between 90 and 472 r. p. m., giving pitch line velocities of 53 to 277 feet per minute. The third, 16 in the diagram, is a true worm, 2¼ inches pitch diameter, lead 1.333, triple thread, speed 200 to 1,442 r. p. m., bronze wheel and hardened steel worm. These figures give a pitch angle of 10° 45′, and a pitch line velocity of 118 to 845 feet per minute. While this

Digitized by Google

worm is entirely successful, it was at first a failure, and was made successful only by careful attention to the materials used.

LIMITING SPEEDS AND PRESSURES.

A very important point connected with worm design, and one on which data are very scarce, is the limiting pressures for various speeds at which cutting begins. The paper by Mr. Lewis contains some information on this subject, and the accompanying table supplied by Mr. Christie, from experiments made by him, supplies the most definite additional data on the subject known to the writer. In all cases the worms were of hardened steel and the worm wheels of cast-iron. Lubrication by an oil bath.

There is real need of a comprehensive series of experiments on this subject. It is obvious enough that a worm, otherwise well designed, might fail from having too high a speed for its load. Were such data at hand it would seem that with existing knowledge of the influence of

Digitized by Google

LIMITING SPEEDS AND PRESSURES OF WORM GEARING.

	Single Thread Worm 1″ Pitch 2⅞ Pitch Diameter				Double Thread Worm 2″ Pitch 2⅞ Pitch Diameter			Double Thread Worm 2½″ Pitch 4½ Pitch Diameter		
Revolutions per minute	128	201	272	425	128	201	272	201	272	425
Velocity at pitch line in feet per minute.....	96	150	205	320	96	150	205	235	319	498
Limiting pressure in pounds.....	1,700	1,300	1,100	700	1,100	1,100	1,100	1,100	700	400

Digitized by Google

the angle of the thread, worm design might be made a matter of comparative certainty. Especially should the behavior of worms at speeds above 200 feet per minute be subjected to further experiment, as it is frequently necessary to use speeds above that figure, and there can be no doubt that higher speeds are entirely feasible if suitable pressures accompany them. The speed as a factor should be kept in mind equally with the pitch angle. A worm may fail because of too high a pitch line velocity as well as because of too low a pitch angle.

The number of cases cited is too few for certainty in drawing general conclusions, but the testimony is unmistakable in its confirmation of the theory of the influence of the angle of the thread. It will be seen that every case having an angle above 12° 30′ was successful, and every case below 9° nnsuccessful, the overlapping of the successful and unsuccessful worms in the intervening region being what is to be expected in the bor-

Digitized by Google

der region between good and bad practice. This band of uncertain results is in fact narrower than we would have any right to expect from a collection of data from miscellaneous sources, and could the inquiry be widened in scope the width of this band would doubtless be increased. As throwing light on these cases it should be remembered that case 16 is known to have been made successful only by careful attention to the material used, the first worms made having been failures, and that 3, which is near 16, and was a failure, had an excessive speed, while 11 at a lower angle, and a success, had a very moderate speed. At a higher speed 11 would probably have failed, and at a lower speed 3 would probably have been a success. It is believed that Fig. 3 points out clearly the nature of the worm problem and the conditions of success in its solution.

Digitized by Google

STEP BEARINGS.

The step bearings of worms have been a source of trouble alongside of the worm itself. It is obvious enough that the increase of the thread angle will relieve the step of wear as well as the worm thread. Expedients are possible with the step, however, which are not available with the worm. Ball and roller step bearings have been extensively tried, and while some have been successful with them, the general results are believed to have been unsatisfactory. The troubles from ball bearings arise from the tendency of the balls to break up under heavy loads and to score the pressure plates, while conical rollers, which geometrical considerations call for, have in some instances made trouble from their outward radial pressure cutting out the confining ring.* The multiple washer thrust bear-

* Mr. C. R. Pratt has had marked success with roller thrust bearings in which the rollers were short cylinders kept in position by a distance plate or cage having suitable openings arranged in spirals. See "The American Machinist," June 23, 1901.

Digitized by Google

ing is used by many, and is undoubtedly entirely successful. Many of the readers of this volume have no doubt seen this pattern of bearing without reflecting upon the principle which lies at the bottom of it. When several loose washers are interposed between the shaft collar and the face of the shaft bearing, it is obvious that slipping may occur between any pair of faces, and that this slipping will take place between those surfaces which at the moment offer the least friction. Should these surfaces from any cause increase their resistance the slipping will be at once transferred to another joint, the various surfaces acting as mutual safety valves to one another, any surface which gets into the condition of incipient heating or cutting being at once relieved by another taking up the work. Fig. 6 shows one of these bearings as made by the Newton Machine Tool Works. The Newton Works formerly followed the usual practice and made the washers *a* alternately of hardened

Digitized by Google

steel and bronze, but consider that they have improved on this by substituting white cast-iron for the steel. These castings are obtained from the malleable iron foundries, and are in fact unannealed malleable castings. Of course these castings cannot be machined, and they are therefore prepared for use by grinding on a cup-shaped emery wheel. They are dropped into a socket on the end of a shaft, which is revolved by hand, and are thus presented to the face of the cup-shaped wheel. This plan results in the grinding marks crossing the faces in all directions, instead of being in circles as in lathe-finished pieces. All mechanics understand the advantage of having the tool marks in a direction different from that of the motion of the parts, which advantage this method of construction secures. Another feature of the Newton bearings consists in making the holes in the washers larger than the shaft on which they are placed. This construction introduces an irregular compound mo-

Digitized by Google

tion of the surfaces upon one another, the advantages of which are well understood. In the Newton washers the holes are $\frac{1}{32}$-inch larger than the shaft, though Mr. Newton considers that this might be increased with probably good results.

Three radial oil grooves are cast in each face of these disks, the use of which is obvious. The Hewes & Phillips step, at the right-hand bearing, will be seen to include three washers, while the left-hand step has lenticular-shaped disks—a construction which has also found favor elsewhere.

Digitized by Google

PART II.

SPIRAL GEARING.

SPIRAL GEARS COMPARED WITH SPUR GEARS—THE DIFFERENT PITCHES.

SPIRAL gears are not to blame for the undoubted fact that they are somewhat troublesome to lay out, the difficulties of the problem being due to the limitations of workshop facilities and not to the geometrical nature of the gears themselves. It is easy to understand and explain the action of an existing pair of spiral gears. More than this it is easy to lay out a pair of such gears which shall exactly meet all the conditions of the case except one—they cannot, except through rare good luck, be made with the appliances at hand. To be more specific, the circum-

Digitized by Google

ference cannot usually be divided into an exact whole number of teeth by any stock cutter, and the real problem becomes the readjusting of the diameters of the gears and the angle of the teeth, so that stock cutters shall make an exact whole number of teeth.

With spur gears it is only necessary to multiply the (circumferential) pitch of the cutter by the number of teeth to be cut to obtain the circumference of the gears. With spiral gears this operation gives the length of a portion of a spiral, or, more properly, helix, wound upon the pitch surface. We do not know the angle of this helix, the diameter of the pitch cylinder upon which it is wrapped or even what part of a complete turn the known portion comprises. The length is known for each gear and nothing more, and it becomes a matter of trial to find the diameters of the gears and the helix angle to suit this portion of the helix and at the same time fill the required center distance.

Digitized by Google

Fig. 8 is a conventional representation of the pitch surface of a spiral gear, the surface being extended beyond the limits of the gear in order that the two helixes with which we are concerned may be shown. The first of these, *a b c d e f*, is the tooth helix and the second, *a g h d i p*, is the normal helix. The tooth helix is of importance because it defines the angle of the teeth. Given the diameter of the pitch surface, the helix may be defined by the angle *k a l* or by the length *a f*, in which it makes a complete turn—that is, by its pitch. For the determination of the speed ratio of a pair of gears the former method is the more convenient, but the tables supplied with universal milling machines which are used in setting up the machine employ the latter method.

In all spiral gear problems we have two pitches to deal with—the pitch of the tooth helix and the pitch of the teeth. The latter may be measured in several ways. First is the value *a n*, measured on the circumference or the *circumfer-*

Digitized by Google

ential pitch, which is analogous to the pitch of spur gears; second is the value *a o* measured on the normal helix or the *normal pitch*, for which the cutters must be selected; third is the value *a r* measured parallel with the axis or the *axial pitch*.* Since the cutters must be selected with reference to the normal pitch the length of the normal helix is naturally of importance in connection with the number of teeth in the gear. The normal pitch multiplied by the number of teeth must naturally equal the length *a g h d* of this helix measured between its intersections *a* and *d* with the helix of a single tooth. Note that the length of the normal helix to be considered is the length *a g h d* between its intersections with the tooth helix and not the length

* Of two mating gears the circumferential pitch of one is equal to the axial pitch of the other, and *vice versa*. The axial and circumferential pitches are of small importance, except in the case of worm gearing. In making a worm we deal with axial pitch, and in making a worm wheel, with circumferential pitch. In such spiral gears as are made with a formed milling cutter (not a hob) we are concerned chiefly with normal pitch.

Digitized by Google

a g h i p q of a complete turn around the cylinder. That this is true may be seen by reference to Fig. 9, in which the angle *k a l* is nearly a right angle. It is apparent from this illustration that the length of the normal helix from *a* to *d* takes in all the teeth and that *a o*, multiplied by the number of teeth, must equal *a h p d* and not *a h p q*. This length *a h p d* is always less than *a h p q*, and usually much less. Fig. 10 *A* is a development of Fig. 9 on a reduced scale, *a d* being the developed length of the normal helix. Fig. 10 *B* and Fig. 10 *C* show how with the same circumferential pitch and the same number of teeth but a reduced value of the angle *k a l*, the length of the normal helix which cuts all the teeth grows shorter until it may make but a small part of a complete turn around the cylinder. It is clear that in all cases the line *a d* cuts all the teeth precisely as does the circumference *a a*, which goes completely around the cylinder. It is also clear that if the normal pitch is de-

Digitized by Google

cided upon at the start, a diameter of cylinder and a helix angle must be found such that the normal pitch, multiplied by the number of teeth, shall equal the length of the normal helix between two intersections with the tooth helix.

It is natural to ask: Why not employ the circumferential pitch and so deal directly with the circumference instead of the normal helix? Because we do not know what it is. The normal pitch is determined by the cutter used, while the circumferential pitch depends also upon the helix angle, and until this angle is known the circumferential pitch is not known.

In the extreme case of a spiral gear in which the helix angle is so small that the gear becomes a single thread worm, as in Fig. 11, points *o* and *d* coincide and the length of the helix between *a* and *d* becomes the normal pitch. It is, however, true as before that the normal pitch, multiplied by the number of teeth, which is now one, is still equal to the length of

Digitized by Google

the normal helix between two intersections with the tooth helix.

A glance at Fig. 10 will show that in gears of the same diameter the length of the normal helix* grows shorter as the angle *k a l* grows less, and hence that it and its gear will contain successively fewer and fewer teeth of the same normal pitch. That is to say, the number of teeth in a gear varies with the helix angle as well as with the diameter and *the number of teeth in two gears of the same normal pitch is not necessarily proportional to the diameters.* In fact, it is never so proportional, except when the angle *k a l* is equal to 45 degrees. *The diametral pitch of the cutters and the diameter of the gear thus do not determine the number of teeth.*

The two facts thus developed are fundamental and will bear re-stating:

First, *The number of teeth is equal to*

---

* "Length of normal helix" is to be understood as meaning the length of that helix between two intersections with the same tooth helix.

Digitized by Google

the length of the normal helix divided by the normal pitch.

Second, *The numbers of teeth in a pair of gears are not proportional to the diameters, except when the angle of the tooth helix is 45 degrees.*

THE SPEED RATIO.

Fig. 12 illustrates the simplest possible case of a pair of spiral gears. The gears are of equal size and the tooth helix has an angle of 45 degrees. Such a pair of gears will obviously run at the same speed —that is, have a speed ratio of 1—and as obviously both will have the same number of teeth. Now, unlike spur gears, there are two ways in which the speed ratio of such a pair of spiral gears may be varied. First, the diameters of the gears may be changed, as with spur gears, the angle of the tooth helix remaining unchanged, as in Fig. 13; and second, the angle of the helix may be changed, the diameters of the gears remaining unchanged, as in Fig. 14. These methods act in very dif-

Digitized by Google

ferent ways. The first method is analogous to the procedure with spur gears. As with spur gears, the circumferential or pitch line speed of the two gears remains, as before the change, equal, but the length of the circumference of the two gears is unequal and the larger one thus has a less number of revolutions than the smaller one. The second method is entirely unlike anything seen in connection with spur gears. By it the pitch line speeds of the two gears are made unequal, and hence, while their diameters are equal, the lower one revolves the more slowly. This points out another fundamental difference between spiral and spur gears: With spiral gears, unless the helix angle is 45 degrees, *the pitch line speeds of two mating gears are not the same.*

The two methods of changing the speed ratio shown in Figs. 13 and 14 may be combined. That is, part of the desired change in speed may be obtained by changing the diameters of the gears and the remainder by changing the angle of

Digitized by Google

the helix. Given the speed ratio and the diameter of one of the gears, we may assume a helix angle and find a diameter for the second gear to go with it which shall give the desired speed ratio and, having done this, a second angle may be assumed and a second diameter be found. There are thus an indefinite number of combinations of angles and diameters which will give the required speed ratio. Note, however, that with the diameter of one gear fixed, every change in the diameter of the other changes the distance between centers, that not every angle of helix can be obtained by the gears which are furnished with universal milling machines, and that if ready-made cutters are to be used, the lengths of both normal helixes must be exact multiples of the normal pitch of the teeth. The problem of designing spiral gears thus consists of finding a pair which shall have a given center distance, helix angles which can be cut with the means at hand, and such a normal pitch that stock cutters can be

Digitized by Google

used. Remove these restrictions and laying out a pair of spiral gears becomes simple. It is, in fact, frequently necessary to remove one of them, namely, the helix angle limitation, by making new gears for the spiral head which shall cut the angle desired.

Geometrically speaking, there is a wide range of choice in the helix angle. As regards the desirability of different angles from the standpoint of durability, the conditions are essentially the same as in worm gearing. Reference to Part I, will show that the most favorable angle for durability is at about 45 degrees. There is, however, but a trifling increase in wear down to 30 degrees, no serious increase down to 20 degrees, and no destructive increase down to about 12 degrees. Where gears are to transmit considerable power the best results should attend the use of angles between 30 and 45 degrees, while angles as low as 20 degrees may be used without hesitation, and as low as 12 degrees if the gears are

Digitized by Google

to run in an oil bath or do light work only. The angle may also be increased above 45 degrees by similar amounts and with similar results.

Fig. 15 is a development of the gears of Fig. 14, the angle α of Fig. 15 being equal to $k\,a\,l$ of Fig. 14, but in reversed position, because in Fig. 14 the upper side of the driver is seen, while in Fig. 15 the direction of the teeth is that of the lower side of the driver.

It is clear that if the driver move in the direction of the arrow it will, while moving the distance $a\,b$, push the driven gear the distance $b\,c$, and the pitch line speeds will have the relation :

$$\frac{\text{p.l. speed follower}}{\text{p.l. speed driver}} = \frac{b\,c}{b\,a}$$
$$= \tan \alpha.$$

If the gears have the same diameters, their number of revolutions will be in the same ratio as their pitch line speeds—that is :

Digitized by Google

$$\frac{\text{rev. follower}}{\text{rev. driver}} = \tan \alpha,$$

or

$$\text{rev. follower} = \text{rev. driver} \times \tan \alpha.$$

If the diameter of the follower be increased, its number of revolutions will be reduced in the same ratio—that is:

$$\text{rev. follower} = \frac{\text{diam. driver}}{\text{diam. follower}} \times \text{rev. driver} \times \tan \alpha,$$

or

$$\frac{\text{rev. follower}}{\text{rev. driver}} = \frac{\text{diam. driver}}{\text{diam. follower}} \times \tan. \alpha,$$

the angle α being taken from the driver.

This is a complete formula for the speed ratio of spiral gears having shafts at right angles. But for the limitations imposed by the use of stock cutters it, together with the fact that the sum of the diameters of the gears must equal twice the center distance, would be all that is required for designing such gears. Note that it differs from the corresponding

Digitized by Google

formula for spur gears only by the introduction of the factor tan α.

THE PRELIMINARY SOLUTION.

The simple formula for the speed given above will be needed repeatedly, and had best be put in algebraic form.

Let r_1 = revolutions of driver,
r_2 = revolutions of follower,
d_1 = diameter of driver,
d_2 = diameter of follower,
α = helix angle of driver.

Then this formula becomes :

$$\frac{r_2}{r_1} = \frac{d_1}{d_2} \tan \alpha \qquad (1)$$

In any actual case the speeds are given and the diameters and helix angle must be found. We may assume a ratio for the diameters and find the angle, or we may assume an angle and find the ratio of diameters. It is desirable to assume the angle first, as on it depends, largely, the durability of the gears. To do this

Digitized by Google

the above formula may be more conveniently written :

$$\frac{d_2}{d_1} = \frac{r_1}{r_2} \tan \alpha \qquad (2)$$

The sum of the diameters must equal twice the center distance, which we may call C. That is :

$$d_1 + d_2 = 2C,$$

or

$$d_2 = 2C - d_1.$$

Substituting this value for d_2 in (2) we obtain :

$$\frac{2\,C - d_1}{d_1} = \frac{r_1}{r_2} \tan \alpha$$

which, solved for d_1, becomes :

$$d_1 = \frac{2C}{\frac{r_1}{r_2} \tan \alpha + 1} \qquad (3)$$

Having assumed a value for α and substituted its tangent and the ratio of the desired speeds in (3), we find a value for d_1, and, having found d_1, d_2 may obviously be found by subtracting d_1 from $2C$.

Digitized by Google

Such a solution is complete in a geometrical sense, and if it were feasible to make a cutter to suit each case, it would be complete in a practical sense also. When, however, we go a step further and find the length of the normal helixes, the probabilities are all against their being exact multiples of the pitch of any stock cutter. The solution so obtained must therefore be considered as provisional and be modified to suit the cutters to be used. When the adjustment to suit the cutters has been made, it is still a matter of chance if the resulting angle can be cut with the gears supplied with the spiral head of a universal milling machine, and again the probabilities are against it. Eventually one of these conditions can always be met exactly, but both of them rarely. If both are to be met exactly or with close accuracy, it is frequently necessary to make new gears for the spiral head.

Digitized by Google

THE LENGTHS OF THE NORMAL HELIXES.

Fig. 16 is the development of a pair of gears placed in the most convenient position for showing the lengths of the normal helixes. The tooth and normal helixes are extended beyond the face of the gears. Let

c_1 = circumference of driver,
c_2 = circumference of follower,
d_1 = diameter of driver,
d_2 = diameter of follower,
l_1 = length of normal helix of driver between intersections with tooth helix,
l_2 = length of normal helix of follower between intersections with tooth helix,
α = tooth helix angle of driver.

Obviously

$$l_1 = c_1 \sin \alpha,$$
$$= \pi d_1 \sin \alpha,$$

or

$$\frac{l_1}{\pi} = d_1 \sin \alpha \qquad (4)$$

Digitized by Google

$$l_2 = c_2 \cos \alpha,$$
$$= \pi d_2 \cos \alpha,$$

or
$$\frac{l_2}{\pi} = d_2 \cos \alpha \qquad (5)$$

Note that (4) and (5) give the lengths of the normal helixes divided by π and not their actual lengths. This is done because, in dealing with diametral pitch cutters the calculations are made less laborious. Dividing (4) by (5) gives :

$$\frac{l_1}{l_2} = \frac{d_1 \sin \alpha}{d_2 \cos \alpha}$$
$$= \frac{d_1}{d_2} \tan \alpha \qquad (6)$$

Comparing (1) with (6) proves what is almost self-evident, that the lengths of the normal helixes are to each other inversely as the number of revolutions, and hence that *a pitch which will exactly divide the short helix will also divide the long one* and that *the numbers of teeth in the gears are inversely as the speeds.*

Digitized by Google

A PRACTICAL EXAMPLE.

An example will best illustrate the actual procedure. Thus assume the conditions of a pair of gears to be :

$$\frac{\text{revolutions of follower}}{\text{revolutions of driver}} = \frac{r_2}{r_1} = \frac{1}{4}$$

and

$$\text{center distance} = C = 4\tfrac{15}{32}$$
$$= 4.468 \text{ inches.}$$

Assume further that a helix angle of 45 degrees would lead to a diameter for the driver which would make it too small for its shaft. We are, at the start, entirely at sea regarding the whole matter; but as an angle of 30 degrees is favorable to durability we may use it as a trial angle and see what it will lead to. Finding the tangent of 30 degrees in a table and substituting it and the value of $\frac{r_1}{r_2}$ in (3) we obtain :

$$d_1 = \frac{2 \times 4.468}{4 \times .57735 + 1}$$
$$= 2.7$$

Digitized by Google

and

$$d_2 = 2 \times 4.468 - 2.7$$
$$= 6.236.$$

From (4) we find

$$\frac{l_1}{\pi} = 2.7 \times .5$$
$$= 1.35$$

and from (5)

$$\frac{l_2}{\pi} = 6.236 \times .866$$
$$= 5.4.$$

These values of d_1, d_2, $\frac{l_1}{\pi}$ and $\frac{l_2}{\pi}$ are the provisional values belonging with 30 degrees for α.

Assume next that it is desired to use cutters of 6 diametral pitch, the circumferential pitch of which is $\frac{\pi}{6} = .5236$. We may find the number of teeth which the normal helixes will contain by dividing their lengths by this circumferential pitch, but

Digitized by Google

$$l \div \frac{\pi}{6} = \frac{l}{\pi} \times 6.$$

That is, the number of teeth of 6 diametral pitch which the provisional normal helixes will contain may be found by multiplying $\frac{l_1}{\pi}$ and $\frac{l_2}{\pi}$ respectively by 6. Performing this operation we obtain :

$$\frac{l_1}{\pi} \times 6 = 1.35 \times 6$$
$$= 8.1$$

and
$$\frac{l_2}{\pi} \times 6 = 5.4 \times 6$$
$$= 32.4.$$

The provisional normal helixes thus contain 8.1 and 32.4 teeth of the desired pitch, and as these numbers are impossible, we take the nearest whole numbers having the desired ratio of 1 to 4, namely, 8 and 32. That is, we decide to shorten the normal helixes until they contain exactly 8 and 32 teeth.

The meaning of this is shown graphi-

Digitized by Google

cally in Fig. 17. Laying down ab and ac to represent the circumferences as found above and drawing the normal helixes at an angle of 30 degrees, we have found that the normal helix ad of the driver will contain 8 teeth and a little more, and the normal helix ae of the follower 32 teeth and a little more. As we cannot have a fraction of a tooth, we decide to cut off the ends of the helixes, making their lengths ad' and ae'.*

FINAL SOLUTION BY CHANGING THE CENTER DISTANCE.

The most obvious way of carrying this out is simply to reduce the diameters of both gears, so as to make their circumferences ab' and ac' instead of ab and ac. This change obviously reduces the center distance, but at this drawing-board

* Should the helixes come out a little short instead of a little long, they would be lengthened instead of shortened. Had the helix of the driver been of a length to contain, say, 8.3 teeth, that of the follower would obviously have contained 33.2 teeth, and, in the correction, more than an entire tooth would have been cut from it.

Digitized by Google

stage of affairs this can often be done, and when it can be done it is the readiest way out of the difficulty. To determine how much to reduce the diameters we may first find the reduced lengths of the normal helixes, by dividing the final numbers of teeth—8 and 32—by 6 and then find the new diameters, or more simply, we may note, what is apparent from Fig. 17, that the lengths of the helixes and of the diameters have been changed in the same ratio as the numbers of teeth.

That is :

$$\frac{\text{final diameter}}{\text{provisional diameter}} = \frac{8}{8.1}$$

or

$$\text{final diameter} = \text{provisional diam.} \times \frac{8}{8.1}$$

That is :

$$\text{final } d_1 = 2.7 \times \frac{8}{8.1}$$
$$= 2.667$$

Digitized by Google

and

$$\text{final } d_2 = 6.236 \times \frac{8}{8.1}$$
$$= 6.159$$

and $d_1 + d_2 = 2.667 + 6.159 = 8.825 =$ twice the new center distance.

GRAPHICAL SOLUTION WITH CHANGED CENTER DISTANCE.

All these determinations may be made graphically as in Fig. 18. Lay off $a\,b = 2\,C = 8\frac{15}{16}$ inches. At any convenient distance lay off the indefinite line $c\,d$ parallel to $a\,b$. At c lay off the provisional angle $\alpha = 30$ degrees. Draw $e\,f$ at any convenient point perpendicular to $c\,d$. Take $e\,f$ in the dividers and step it off from e toward d as many times as will represent the ratio of the desired speed of the driver divided by that of the follower. That is, in the present case, lay off $e\,f$ 4 times above e and thus obtain d. Draw $c\,a$ and $d\,b$ and extend them till they meet

Digitized by Google

at g.* Draw $g\,e$, giving $a\,h$ and $b\,h$, which are provisional diameters of driver and follower respectively. Draw $h\,p$ perpendicular to $a\,b$, at h lay down $h\,k$ and $h\,l$ to repeat α, and from h strike arcs $a\,k$ and $b\,l$. Draw $k\,o$ and $n\,l$ perpendicular to $a\,b$, and we have the provisional values,

$$a\,h = d_1$$
$$b\,h = d_2$$
$$h\,o = \frac{l_1}{\pi}$$
$$h\,n = \frac{l_2}{\pi}$$

Scale $h\,o$ and $h\,n$ and multiply them by the diametral pitch number—6. If the results are not whole numbers, as they usually are not, select the nearest whole numbers having the desired speed ratio, and they are the final numbers of teeth. Divide these numbers by the diametral pitch number to obtain the final values

* Had $c\,d$ been taken shorter than $a\,b$, g would have fallen to the left of the diagram, but the construction would otherwise have been unchanged.

Digitized by Google

of $\frac{l_1}{\pi}$ and $\frac{l_2}{\pi}$ and lay them down as $h\,o'$ and $h\,n'$. Draw $o'\,k'$ and $l'\,n'$ and $k'\,a'$ and $l'\,b'$, giving:

$a'\,h$ = the final d_1,
$b'\,h$ = the final d_2,
$a'\,b'$ = twice the new center distance.

FINAL SOLUTION WITH UNCHANGED CENTER DISTANCE.

If the center distance cannot be varied, the condition of things is shown in Fig. 19. Having found that the provisional normal helixes will not contain an exact number of teeth, and cut them off and obtained the smaller circumferences $a\,b'$ and $a\,c'$ of Fig. 17, the problem becomes to find a new value of α, indicated in Fig. 19, as α', which shall give such diameters as to restore the old center distance. That is, $a\,b'' + a\,c''$ of Fig. 19 must be equal to the original $a\,b + a\,c$ of Fig. 17. It will be seen by a glance at Fig. 19 that the reduced value of α in-

Digitized by Google

creases the diameter of the driver, but reduces that of the follower.

It is probable that the correct angle and diameters for this case can be found only by trial. From (4) we have:

$$d_1 = \frac{l_1}{\pi \sin \alpha} \tag{7}$$

and from (5)

$$d_2 = \frac{l_2}{\pi \cos \alpha} \tag{8}$$

We also have:

$$d_1 + d_2 = 2\,C;$$

that is $$\frac{l_1}{\pi \sin \alpha} + \frac{l_2}{\pi \cos \alpha} = 2\,C,$$

which easily reduces to:

$$1 + \frac{l_2}{l_1} \tan \alpha = \frac{2\,C}{\frac{l_1}{\pi}} \sin \alpha \tag{9}$$

To solve this equation we know that $\frac{l_2}{l_1}$ = the speed ratio = 4 and in a preceding section we found that the cor-

Digitized by Google

rected value of $\frac{l_1}{\pi}$ bears the same relation to the provisional value that the corrected number of teeth bears to the provisional number. That is, the corrected value of $\frac{l_1}{\pi} = 1.35 \times \frac{8}{8.1} = 1.33$. Substituting these values and the value of C, the only unknown quantity is α, but, from the form of the equation, α can be found only by trial and error, the result of each trial being a closer and closer approximation to the truth. The operation is simple enough, but it involves the repeated multiplication of decimals. For the earlier steps a slide rule will greatly abbreviate the work, while with a Sexton's omnimeter an accuracy can be obtained sufficient for all the steps and a piece of drudgery be converted into an exhilarating chase. The results which follow were obtained with an omnimeter. Trying the provisional angle of 30 degrees in order to note the result and making the substitutions in (9) we obtain :

Digitized by Google

$$1 + 4 \times .577 = 6.702 \times .5$$

or $$3.308 = 3.351.$$

This is not correct, as we knew it would not be. The right-hand number is larger than the left-hand number, which will always be the case if our trial value of α is too large, and *vice versa* if it is too small. Trying 28 degrees we obtain :

$$1 + 4 \times .532 = 6.702 \times .469$$

or $$3.13 = 3.145.$$

The right-hand number is still too large, showing 28 degrees to be too large. Trying 26 degrees we obtain :

$$1 + 4 \times .488 = 6.702 \times .438$$

or $$2.953 = 2.935.$$

The right-hand number is now too small, showing that 26 degrees is too small. Trying 26 degrees 30 minutes we obtain :

$$1 + 4 \times .499 = 6.702 \times .446$$

or $$3. = 2.99$$

Digitized by Google

This angle is still too small, though obviously very nearly correct. Trying 26 degrees and 40 minutes we obtain :

$$1 + 4 \times .502 = 6.702 \times .449$$

or $$3.01 = 3.01$$

Within the limits of accuracy of the omnimeter this is correct, and as that instrument shows the effect of so small a change in the angle as 10 minutes the result is obviously close enough. Having found the angle we are now in shape to find the final diameters. Substituting in (7) and (8) we obtain :

$$d_1 = \frac{1.333}{.4488}$$
$$= 2.971$$

and $$d_2 = \frac{5.333}{.8936}$$
$$= 5.968$$

and $5.968 + 2.971 = 8.939$, which is twice the required center distance as closely as can be expected.

Digitized by Google

GRAPHICAL SOLUTION WITH UNCHANGED CENTER DISTANCE.

These determinations may also be made graphically, as shown in Fig. 20, which repeats the construction of Fig. 18 up to the finding of the provisional values of $a\,h$ and $b\,h$.

In Fig. 18 h was a fixed point, while a and b were not. In the present case a and b are fixed, but h is not, and to find $\frac{l_1}{\pi}$ and $\frac{l_2}{\pi}$ in the present case it is better to lay off α at a and b instead of at h, as was done in Fig. 18. Therefore lay down α at a and b, as shown, and strike arcs $h\,k$ and $h\,l$. Draw $k\,o$ and $l\,n$, giving the provisional values :

$$a\,o = \frac{l_1}{\pi}$$

$$b\,n = \frac{l_2}{\pi}$$

Measure these distances and multiply them by the diametral pitch number—in this case 6—to find the numbers of teeth

Digitized by Google

going with the assumed value of α. If, as is usually the case, the products are not whole numbers, take the nearest whole numbers having the ratio of the desired speeds, divide them by the diametral pitch number and obtain the corrected values of $\frac{l_1}{\pi}$ and $\frac{l_2}{\pi}$. Lay off $a\,o'$ and $b\,n'$ equal to these corrected values. Assume a new trial angle, indicated as α', and lay it down at a and b. Draw $o'\,k'$ and $n'\,l'$, and through the intersections k' and l' draw the dotted arcs. If these arcs meet in tangency at h', then we have the final values :

$$a\,h' = d_1$$

and

$$b\,h' = d_2$$

If the arcs do not thus meet in tangency, assume another value for α and try again.

Graphical methods are sufficiently accurate for many purposes, especially if laid out upon an enlarged scale, and if it is remembered that if the values used for

Digitized by Google

$\frac{l_1}{\pi}$ and $\frac{l_2}{\pi}$ are a little short of the true values, the shortage will be divided among the teeth with the only result of a little slackness in the teeth.

FINDING THE PITCH OF THE TOOTH HELIX.

It now only remains to find the pitch of the tooth helixes in order to set up the machine. In Fig. 16 let

p_1 = pitch of tooth helix of driver,
p_2 = pitch of tooth helix of follower;

then
$$p_1 = c_1 \tan \alpha,$$
$$= \pi d_1 \tan \alpha,$$

and
$$p_2 = c_2 \cot \alpha,$$
$$= \pi d_2 \cot \alpha.$$

Inserting the final values of d_1, d_2, and α we obtain :

$$p_1 = \pi \times 2.971 \times .502$$
$$= 4.684,$$

and
$$p_2 = \pi \times 5.968 \times 1.991$$
$$= 37.33.$$

Digitized by Google

These values may be found graphically as in Fig. 21. Lay down α and make



FIG. 21.—FINDING THE PITCH OF THE TOOTH HELIX.

$ab = \pi d_1$ when $bc = p_1$. Find $ef = \pi d_2$ and $ae = p_2$.

SPECIAL SOLUTION FOR A HELIX ANGLE OF 45 DEGREES.

Remembering that $\frac{l_2}{l_1} = \frac{r_1}{r_2}$, the latter fraction may be substituted for the former in (9) together with the assumed value of α and the provisional value of $\frac{l_1}{\pi}$

Digitized by Google

be thus found without first finding the provisional values of d_1 and d_2. The final values of d_1 and d_2 may then be found from (7) and (8). Such a solution is in some respects neater than the one given, but it is believed to be less easily followed and comprehended, and, moreover, it does not, for the general case, furnish the basis of so good a graphical solution. This method is at its best in the case of a helix angle of 45 degrees, although this angle does not differ from any other in requiring a change in the center distance if it is to be adhered to. In the nature of the case, if we deny ourselves the liberty of changing the angle, the only recourse is to correct the length of the helix by changing the diameters. As this angle is used more than any other—perhaps more than all others—this solution for it is given.

Remembering that in (9) $\frac{l_2}{l_1} = \frac{r_1}{r_2}$, that $\tan 45° = 1$, and that $\sin 45° = .7071$,

Digitized by Google

that equation becomes *for this angle only:*

$$1 + \frac{r_4}{r_2} = \frac{1.4142\ C}{\frac{l_1}{\pi}}$$

which may be made to read :

$$\frac{l_1}{\pi} = \frac{1.4142\ C}{1 + \frac{r_1}{r_2}} \qquad (10)$$

Inserting sin $45° = .7071$ in (7) we have :

$$d_1 = \frac{\frac{l_1}{\pi}}{.7071} \qquad (11)$$

Equations (10) and (11) are all that are needed for solving any case having this helix angle.

Taking up the preceding problem again and solving it for this angle, we have from (10) for the provisional value :

$$\frac{l_1}{\pi} = \frac{1.4142 \times 4.468}{1 + 4}$$
$$= 1.2637.$$

Digitized by Google

Multiplying this by the diametral pitch of the cutter to be used, we obtain :

$$1.2637 \times 6 = 7.58$$

as the provisional number of teeth in the driver. As it is an impossible number, we select 8 as the number of teeth and, dividing it by 6, we obtain :

$$\frac{8}{6} = 1.333$$

as the final value of $\frac{l_1}{\pi}$. Substituting this in (11), we obtain :

$$d_1 = \frac{1.333}{.7071}$$
$$= 1.885$$

as the final value of the diameter of the driver. The diameter and number of teeth of the follower for an angle of 45 degrees are found by multiplying the diameter and number of teeth of the driver by the speed ratio. That is :

$$d_2 = 1.885 \times 4$$
$$= 7.540$$

Digitized by Google

and

$$\text{number of teeth in follower} = 8 \times 4$$
$$= 32.$$

Finally

$$d_1 + d_2 = 1.885 + 7.54$$
$$= 9.425$$
$$= \text{twice the final center distance.}$$

GRAPHICAL SOLUTION FOR A HELIX ANGLE OF 45 DEGREES.

The graphical solution for this angle is simplified still more than the analytical one.

In case the adjustment to suit stock cutters is to be made by changing the diameters of the gears, that adjustment can be made as in Fig. 22, which repeats essentially, Fig. 17. Laying down the provisional values of the diameters at *a b* and *a c* and drawing *d e* at the helix angle with the base line, the perpendiculars *b d* and *c e* to the normal helix line determine *a d* and *a e*, the provisional lengths of the normal helixes divided by π.

Digitized by Google

Changing these lengths to $a\,d'$ and $a\,e'$, such that when multiplied by the diametral pitch number of the cutter the results are whole numbers in the ratio of the required speeds, and drawing $d'\,b'$ and $e'\,c'$ gives $a\,b'$ and $a\,c'$, the corrected diameters.

If $\alpha = 45$ degrees the helix line becomes $f\,g$ and, with $b\,h$ perpendicular to it, $a\,b$ becomes equal to $a\,h$. In other words, instead of laying off the diameter lines at right angles to one another, they may, in this case, for purposes of determination, be laid off upon a straight line. This fact, in connection with the further fact that with a tooth angle of 45 degrees the diameters of the gears are inversely as the speeds, leads directly to the simple diagram given in Fig. 23, which is all that is required for determining graphically any pair of spiral gears having this tooth angle.

In Fig. 23 lay down $a\,b$ equal to twice the provisional center distance. Divide it at c into two parts the lengths of which

Digitized by Google

are to each other in the ratio of the speeds. Draw de at an angle of 45 degrees with ab and draw ad and be at right angles with de, giving cd and ce the provisional lengths of the normal helixes divided by π. Multiply these lengths by the diametral pitch number. If the results are not whole numbers take the nearest whole numbers having the ratio of the desired speeds, which are, respectively, the numbers of teeth in the gears. Divide these numbers by the diametral pitch numbers and lay down cd' and ce' equal in inches of length to the quotients. Draw $d'a'$ and $e'b'$ perpendicular to de, and we have:

ca' = final diameter of one gear,
cb' = final diameter of the other gear,
$a'b'$ = twice the final center distance.

THE SELECTION OF THE CUTTER.*

There is but one more question which may be mentioned, and that is the selec-

* By J. N. Le Conte in the "American Machinist."

Digitized by Google

tion of the cutter for the spiral gear. If we consider a helix drawn upon a cylinder and then imagine a plane cutting that cylinder normal to the helix at any point, the plane will cut from the cylinder an ellipse having one extremity of its minor axis at the point where the helix is cut by the plane. The minor axis of this ellipse will be $2R$ and the major axis $\frac{2R}{\cos \alpha}$. If we cut a spiral gear in the same way at a point midway between two teeth, the form of the space shown will be the true normal shape which the cutter must be, and the above ellipse will be cut from the pitch cylinder. Now the curvature of this normal section of the gear at the point indicated must be the same as the curvature of the ellipse at the extremity of its minor axis. If we call the major and minor axes of an ellipse $2a$ and $2b$, respectively, the radius of curvature at the extremity of the minor axis is $\rho_0 = \frac{a^2}{b}$.

Digitized by Google

But in our case $a = \frac{R}{\cos \alpha}$, and $b = R$,

Hence : $$\rho_0 = \frac{R}{\cos^2 \alpha}.$$

This is the *radius* of what might be called the "oscillating spur gear." The number of teeth on this gear will be :

$$N_0 = 2 P \rho_0 = \frac{2 P R}{\cos^2 \alpha}.$$

But on the spiral gear itself we have :

$$N = 2 P R \cos \alpha$$

Hence : $$N_0 = \frac{N}{\cos^3 \alpha}$$

and not $\frac{N}{\cos^2 \alpha}$ as sometimes stated.

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google



IREAD ANG
ES FROM F

feet,	steel	worm	and	cast-iron	gear.
"	"	"	"	"	"
"	"	"	"	"	"
"	"	"	"	"	"
"	"	"	"	bronze	"
"	"	"	"	"	"
"	"	"	"	"	"
"	cast-iron	"	"	cast-iron	"
"	steel	"	"	bronze	"
"	"	"	"	cast-iron	"
"	"	"	"	"	"
"	"	"	"	bronze	"
"	"	"	"	"	"
"	cast-iron	"	"	cast iron	"
"	"	"	"	"	"
"	steel	"	"	bronze	"
"	material unknown				
"	"		"		

e the same worm at different speeds;
ie has no quantitative significance.

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google



ican Machinist

RS DEVELOPED.

Digitized by Google

Digitized by Google



Digitized by Google

Digitized by Google



VARIABLE CENTER DISTANCE.

Digitized by Google

Digitized by Google



FIG. 19.—ADJUSTING THE DIAMETERS WHEN THE CENTER DISTANCE IS FIXED.

Digitized by Google

Digitized by Google



WITH FIXED CENTER DISTANCE.

Digitized by Google

Digitized by Google



FIG. 22.—RELATION OF NORMAL HELIX AND DIAMETER IN SPIRAL GEARS HAVING A TOOTH ANGLE OF 45 DEGREES.

Digitized by Google

Digitized by Google



FIG. 23.—SIMPLE GRAPHICAL SOLUTION FOR SPIRAL GEARS HAVING A TOOTH ANGLE OF 45 DEGREES.

Digitized by Google

Digitized by Google

CATALOGUE

OF THE

SCIENTIFIC PUBLICATIONS

OF

D. VAN NOSTRAND COMPANY,

23 MURRAY STREET AND 27 WARREN STREET, N. Y.

A. B. C. CODE. (See Clausen-Thue.)

ABBOTT (A. V.). The Electrical Transmission of Energy. A Manual for the Design of Electrical Circuits. Second edition, revised. Fully illustrated. 8vo, cloth..... $4 50

ABBOT (Gen'l HENRY L.). The Defence of the Seacoast of the United States. Lectures delivered before the U. S. Naval War College. 8vo, red cloth. 2 00

ADAMS (J. W.). Sewers and Drains for Populous Districts. Embracing Rules and Formulas for the dimensions and construction of works of Sanitary Engineers. Fifth edition. 8vo, cloth. 2 50

A1. CODE. (See Clausen-Thue.)

AIKMAN (C. M., Prof.). Manures and the Principles of Manuring. 8vo, cloth..... 2 50

ALEXANDER (J. H.). Universal Dictionary of Weights and Measures, Ancient and Modern, reduced to the Standards of the United States of America. New edition, enlarged. 8vo, cloth..... 3 50

ALEXANDER (S. A.). Broke Down: What Should I Do? A Ready Reference and Key to Locomotive Engineers and Firemen, Round House Machinists, Conductors, Train Hands and Inspectors. With 5 folding plates. 12mo, cloth..... 1 50

ALLEN (C. F.). Tables for Earthwork Computation. 8vo, cloth 1 50

Digitized by Google

ANDERSON (J. W.). The Prospector's Hand-book; A Guide for the Prospector and Traveller in search of Metal-bearing or other Valuable Minerals. Seventh edition, thoroughly revised and much enlarged. 8vo, cloth..... 1 50

ANDERSON (WILLIAM). On the Conversion of Heat into Work. A Practical Hand-book on Heat-Engines. Third edition. Illustrated. 12mo, cloth. 2 25

ANDES (LOUIS). Vegetable Fats and Oils; their Practical Preparation, Purification and Employment for various purposes. Their Properties. Adulteration and Examination. A Hand-book for Oil Manufacturers and Refiners, Candle, Soap and Lubricating Oil Manufacturers and the Oil and Fat Industry in general. Translated from the German. With 94 illustrations. 8vo, cloth..... 4 00

—— Animal Fats and Oils. Their Practical Production, Purification and Uses for a great variety of purposes, their Properties, Falsification and Examination. A Hand-book for Manufacturers of Oil and Fat Products, Soap and Candle Makers, Agriculturists, Tanners, etc. Translated by Charles Salter. With 62 illustrations. 8vo, cloth..... net 4 00

ARNOLD (Dr. R.). Ammonia and Ammonium Compounds. A Practical Manual for Manufacturers, Chemists, Gas Engineers and Drysalters. Second edition. 12mo, cloth..... 2 00

ARNOLD (E.). Armature Windings of Direct Current Dynamos. Extension and Application of a General Winding Rule. Translated from the original German by Francis B. DeGress, M. E. With numerous illustrations..... (In Press.)

ATKINSON (PHILIP). The Elements of Electric Lighting, including Electric Generation. Measurement, Storage, and Distribution. Ninth edition. Fully revised and new matter added. Illustrated. 12mo, cloth..... 1 50

—— The Elements of Dynamic Electricity and Magnetism. Third edition. 120 illustrations. 12mo, cloth..... 2 00

Digitized by Google

ATKINSON (PHILIP). Power Transmitted by Electricity and its Application by the Electric Motor, including Electric Railway Construction. New edition, thoroughly revised, and much new matter added. Illustrated 12mo, cloth.... ..... 2 00

—— Elements of Static Electricity, with full description of the Holtz and Topler Machines, and their mode of operating. Illustrated. 12mo, cloth 1 50

AUCHINCLOSS (W. S.). Link and Valve Motions Simplified. Illustrated with 29 woodcuts and 20 lithographic plates, together with a Travel Scale, and numerous useful tables, Thirteenth edition, revised. 8vo, cloth..... .... 2 00

AXON (W. E. A.). The Mechanic's Friend. A Collection of Receipts and Practical Suggestions. 12mo, cloth 1 50

BACON (F. W.). A Treatise on the Richards, Steam-Engine Indicator, with directions for its use. By Charles T. Porter. Revised, with notes and large additions as developed by American practice; with an appendix containing useful formulæ and rules for engineers. Illustrated. Fourth edition. 12mo, cloth 1 00

BADT (F. B.). New Dynamo Tender's Hand book. With 140 illustrations. 18mo, cloth..... 1 00

—— Bell Hangers' Hand-book. With 97 illustrations. Second edition. 18mo, cloth..... .... 1 00

—— Incandescent Wiring Hand-book. With 35 illustrations and five tables. Fifth edition. 18mo, cloth. 1 00

—— Electric Transmission Hand-book. With 22 illustrations and 27 tables. 18mo, cloth 1 00

BALE (M. P.). Pumps and Pumping. A Hand-book for Pump Users. 12mo, cloth. 1 00

BARBA (J.). The Use of Steel for Constructive Purposes. Method of Working, Applying, and Testing Plates and Bars With a Preface by A. L Holley, C. E. 12mo, cloth 1 5

BARKER (ARTHUR H.). Graphic Methods of Engine Design. Including a Graphical Treatment of the Balancing of Engines. 12mo, cloth.... . 1 5

Digitized by Google

BARNARD (F. A. P.). Report on Machinery and Processes of the Industrial Arts and Apparatus of the Exact Sciences at the Paris Universal Exposition, 1867. 152 illustrations and 8 folding plates. 8vo, cloth 5 00

BARNARD (JOHN H.). The Naval Militiaman's Guide. Full leather, pocket form 1 25

BARWISE (SIDNEY, M. D., London). The Purification of Sewage. Being a brief account of the Scientific Principles of Sewage Purification and their Practical Application. 12mo, cloth. Illustrated. 2 00

BAUMEISTER (R.). The Cleaning and Sewage of Cities. Adapted from the German with permission of the author. By J. M. Goodell, C. E. Second edition, revised and corrected, together with an additional appendix. 8vo, cloth. Illustrated..... 2 00

BEAUMONT (ROBERT). Color in Woven Design. With 32 Colored Plates and numerous original illustrations. Large 12mo..... 7 50

BEAUMONT, W. and DUGALD CLERK. Autocars and Horseless Carriages..... .....(In Press.)

BECKWITH (ARTHUR). Pottery. Observations on the Materials and Manufacture of Terra-Cotta, Stoneware, Fire-Brick, Porcelain, Earthenware, Brick, Majolica, and Encaustic Tiles. 8vo, paper. Second edition 60

BERNTHSEN (A.). A Text-Book of Organic Chemistry. Translated by George M'Gowan, Ph. D. Third English edition. Revised and extended by author and translator. Illustrated. 12mo, cloth..... 2 50

BERTIN (L. E.). Marine Boilers: Their Construction and Working, dealing more especially with Tubulous Boilers. Translated by Leslie S. Robertson, Upward of 250 illustrations. Preface by Sir William White. 8vo, cloth. Illustrated..... 7 50

BIGGS (C. H. W.). First Principles of Electricity and Magnetism. Being an attempt to provide an Elementary Book for those intending to enter the profession of Electrical Engineering. Second edition. 12mo, cloth. Illustrated..... 2 00

Digitized by Google

BLAKE (W. P.). Report upon the Precious Metals. Being Statistical Notices of the principal Gold and Silver producing regions of the world, represented at the Paris Universal Exposition. 8vo, cloth. 2 00

—— Ceramic Art. A Report on Pottery, Porcelain, Tiles, Terra-Cotta, and Brick. 8vo, cloth..... 2 00

BLAKESLEY (T. H.). Alternating Currents of Electricity. For the use of Students and Engineers. Third edition, enlarged. 12mo, cloth..... .. .... 1 50

BLOUNT (BERTRAM). Electro-Metallurgy ..... (In Press.)

BLYTH (A. WYNTER, M. R. C. S., F. C. S.). Foods: their Composition and Analysis. A Manual for the use of Analytical Chemists, with an Introductory Essay on the History of Adulterations, with numerous tables and illustrations. Fourth edition, revised and enlarged. 8vo, cloth 7 50

—— Poisons: their Effects and Detection. A Manual for the use of Analytical Chemists and Experts, with an Introductory Essay on the growth of Modern Toxicology. Third edition, revised and enlarged. 8vo, cloth..... .... 7 50

BODMER (G. R.). Hydraulic Motors; Turbines and Pressure Engines, for the use of Engineers, Manufacturers and Students. Second edition, revised and enlarged. With 204 illustrations. 12mo, cloth..... 5 00

BOILEAU (J. T.). A New and Complete Set of Traverse Tables. Showing the Difference of Latitude and Departure of every minute of the Quadrant and to five places of decimals. 8vo, cloth. 5 00

BOTTONE (S. R.). Electrical Instrument Making for Amateurs. A Practical Hand-book. With 48 illustrations. Fifth edition, revised. 12mo, cloth..... 50

—— Electric Bells, and all about them. A Practical Book for Practical Men. With more than 100 illustrations. 12mo, cloth. Fourth edition, revised and enlarged..... 50

—— The Dynamo: How Made and How Used. A Book for Amateurs. Eighth edition. 12mo. cloth... 1 00

Digitized by Google

BOTTONE (S. R.). Electro Motors: How Made and How Used. A Hand-book for Amateurs and Practical Men. Second edition. 12mo, cloth..... 50

BONNEY (G. E.). The Electro-Platers' Hand-book. A Manual for Amateurs and Young Students on Electro-Metallurgy. 60 illustrations, 12mo, cloth.. 1 20

BOW (R. H.). A Treatise on Bracing. With its application to Bridges and other Structures of Wood or Iron. 156 illustrations. 8vo, cloth..... 1 50

BOWSER (Prof. E. A.). An Elementary Treatise on Analytic Geometry. Embracing Plane Geometry, and an Introduction to Geometry of three Dimensions. 12mo, cloth. Nineteenth edition..... 1 75

—— An Elementary Treatise on the Differential and Integral Calculus. With numerous examples. 12mo, cloth. Sixteenth edition.... ..... 2 25

—— An Elementary Treatise on Analytic Mechanics. With numerous examples. 12mo, cloth. Twelfth edition..... .... 3 00

—— An Elementary Treatise on Hydro-Mechanics. With numerous examples. 12mo, cloth Fifth edition..... 2 50

—— A Treatise on Roofs and Bridges. With Numerous Exercises. Especially adapted for school use. 12mo, cloth. Illustrated.....net 2 25

—— Academic Algebra. Third edition. 12mo, cloth.. 1 25

—— College Algebra. Fourth edition. 12mo, cloth.. 1 75

—— Elements of Plane and Solid Geometry. 12mo, cloth. Second edition..... 1 40

BOWIE (AUG. J., Jun., M. E.). A Practical Treatise on Hydraulic Mining in California. With Description of the Use and Construction of Ditches, Flumes, Wrought-iron Pipes and Dams; Flow of Water on Heavy Grades, and its Applicability, under High Pressure, to Mining. Fifth edition. Small quarto, cloth. Illustrated..... 5 00

BURGH (N. P.). Modern Marine Engineering, applied to Paddle and Screw Propulsion. Consisting of 36 colored plates, 259 practical woodcut illustrations,

Digitized by Google

and 403 pages of descriptive matter. The whole being an exposition of the present practice of James Watt & Co., J. & G. Rennie, R. Napier & Sons, and other celebrated firms. Thick quarto, half morocco. 10 00

BURT (W. A.). Key to the Solar Compass, and Surveyor's Companion. Comprising all the rules necessary for use in the field; also description of the Linear Surveys and Public Land System of the United States. Notes on the Barometer, Suggestions for an Oufit for a Survey of Four Months, etc. Fifth edition. Pocket-book form, tuck 2 50

CALDWELL, (G. C.), and A. A. BRENEMAN. Manual of Introductory Chemical Practice. For the use of Students in Colleges and Normal and High Schools. Fourth edition, revised and corrected. 8vo, cloth Illustrated..... .... 1 50

CAMPIN (FRANCIS). On the Construction of Iron Roofs. A theoretical and Practical Treatise, with wood cuts and Plates of Roofs recently executed. 8vo, cloth..... .... 2 00

CARTER (E. T.). Motive Power and Gearing for Electrical Machinery. A Treatise on the Theory and Practice of the Mechanical Equipment of Power Stations for Electric supply and for Electic Traction. 8vo, cloth. Illustrated..... .... 5 00

CHAMBER'S MATHEMATICAL TABLES, consisting of logarithms of Numbers 1 to 108,000, Trigonometrical, Nautical, and other tables. New edition. 8vo, cloth..... .... 1 75

CHAUVENET (Prof. W.). New Method of Correcting Lunar Distances, and Improved Method of Finding the Error and Rate of a Chronometer, by Equal Altitudes. 8vo, cloth 2 00

CHRISTIE (W. WALLACE). Chimney Design and Theory. A Book for Engineers and Architects, with numerous half-tone illustrations and plates of famous chimneys. 12mo, cloth..... ..... 3 00

CHURCH (JOHN A.). Notes of a Metallurgical Journey in Europe. 8vo, cloth..... 2 00

CLARK D. (KINNEAR, C. E.). A Manual of Rules, Tables and Data for Mechanical Engineers. Based

Digitized by Google

on the most recent investigations. Illustrated with numerous diagrams. 1,012 pages. 8vo, cloth. Sixth edition 5 00
Half morocco 7 50

CLARK D. (KINNEAR, C. E.). Fuel; its Combustion and Economy, consisting of abridgements of Treatise on the Combustion of Coal. By C. W. Williams; and the Economy of Fuel, by T. S. Prideaux. With extensive additions in recent practice in the Combustion and Economy of Fuel, Coal, Coke, Wood, Peat, Petroleum, etc. Fourth edition. 12mo, cloth..... 1 50

—— The Mechanical Engineer's Pocket-book of Tables, Formulæ, Rules and Data. A Handy Book of Reference for Daily Use in Engineering Practice. 16mo, morocco. Second edition 3 00

—— Tramways, their Construction and Working, embracing a comprehensive history of the system, with accounts of the various modes of traction, a description of the varieties of rolling stock, and ample details of Cost and Working Expenses. Second edition. Re-written and greatly enlarged, with upwards of 400 illustrations. Thick 8vo. cloth. 9 00

—— The Steam Engine. A Treatise on Steam Engines and oilers; comprising the Principles and Practice of the Combustion of Fuel, the Econom cal Generation of Steam, the Construction of Steam Boilers, and the Principles, Construction and Performance of Steam Engines, Stationary, Portable, Locomotive and Marine, exemplified in Engines and Boilers of recent date. 1,300 figures in the text, and a series of folding plates drawn to scale. 2 vols. 8vo, cloth. 15 00

CLARK (JACOB M.). A new System of Laying Out Railway Turn-outs instantly, by inspection from Tables. 12mo, leatherette..... 1 00

CLAUSEN-THU (W.). The A. B. C. Universal Commercial Electric Telegraphic Code, especially adapted for the use of Financiers, Merchants, Ship owners, Brokers, Agent, etc. Fourth edition 8vo, cloth. 5 00

—— The A1 Universal Commercial Electric Telegraphic Code. Over 1,240 pp., and nearly 90,000 variations. 8vo, cloth..... 7 50

Digitized by Google

CLEEMANN (THOS. M.). The Railroad Engineer's Practice. Being a Short but Complete Description of the Duties of the Young Engineer in the Preliminary and Location Surveys and in Construction. Fourth edition. Revised and enlarged. Illustrated. 12mo, cloth 1 50

CLERK (DUGALD). Auto-cars or Horseless Vehicles. About 300 pp, 60 illustrations..... ..(In Press.)

CLEVENGER (S. R.). A Treatise on the Method of Government Surveying as prescribed by the U. S. Congress and Commissioner of the General Land Office, with complete Mathematical, Astronomical and Practical Instructions for the use of the United States Surveyors in the field. 16mo, morocco... ... 2 50

COFFIN (Prof. J. H. C.). Navigation and Nautical Astronomy. Prepared for the use of the U. S. Naval Academy. New Edition. Revised by Commander Charles Belknap. 52 woodcut illustrations. 12mo, cloth ....net. 3 50

COLE (R. S., M. A.). A Treatise on Photographic Optics. Being an account of the Principles of Optics, so far as they apply to Photography. 12mo, cloth, 103 illustrations and folding plates..... 2 50

COLLINS (JAS. E.). The private Book of Useful Alloys, and Memoranda for Goldsmiths, Jewelers, etc. 18mo, cloth 50

CORNWALL (Prof. H. B.). Manual of Blow-pipe Analysis, Qualitative and Quantitative. With a Complete System of Descriptive Mineralogy. 8vo, cloth. With many illustrations..... 2 50

CRAIG (B. F.). Weights and Measures. An Account of the Decimal System, with Tables of Conversion for Commercial and Scientific Uses. Square 32mo, limp cloth 50

CROCKER (F. B.). Electric Lighting. A Practical Exposition of the Art, for use of Engineers, Students, and others interested in the Installation or Operation of Electrical Plants. Second edition. Revised. 8vo, cloth. Vol. 1. The Generating Plant 3 00
Vol. 2.... .... (In Press.)

Digitized by Google

CROCKER, (F. B.), and S. S. WHEELER. The Practical Management of Dynamos and Motors. Fourth edition (eighth thousand). Revised and enlarged With a special chapter by H. A. Foster. 12mo, cloth. Illustrated..... 1 00

CUMMING (LINNÆUS, M. A.). Electricity treated Experimentally. Fo the use of Schools and Students New edition. 12mo, cloth..... 1 50

DAVIES (E. H.). Machinery for Metalliferous Mines. A Practical Treatise for Mining Engineers, Metallurgists and Manufacturers. With upwards of 300 illustrations. 8vo, cloth 5 00

DAVIS (JOHN W., C. E.). Formulæ for the Calculation of Railroad Excavation and Embankment, and for finding Average Haul. Second edition. Octavo, half roan..... 1 50

DAY (CHARLES). The Indicator and its Diagrams. With Chapters on Engine and Boiler Testing; Including a Table of Piston Constants compiled by W. H. Fowler. 12mo, cloth. 125 illustrations..... 2 00

DERR (W. L.). Block Signal Operation. A Practical Manual. Oblong, cloth..... 1 50

DIXON (D. B.). The Machinist's and Steam Engineer's Practical Calculator. A Compilation of Useful Rules and Problems arithmetically solved, together with General Information applicable to Shop-Tools, Mill-Gearing, Pulleys and Shafts, Steam-Boilers and Engines. Embracing valuable Tables and Instruction in Screw cutting, Valve and Link Motion, etc. 16mo, full morocco, pocket form..... 1 25

DODD (GEO.). Dictionary of Manufactures, Mining, Machinery, and the Industrial Arts. 12mo, cloth ... 1 50

DORR (B. F.). The Surveyor's Guide and Pocket Table Book. 18mo, morocco flaps. Third edition... 2 00

DRAPER (C. H.). An Elementary Text Book of Light, Heat and Sound, with Numerous Examples. Fourth edition. 12mo, cloth. Illustrated..... 1 00

—— Heat and the Principles of Thermo-Dynamics. With many illustrations and numerical examples. 12mo, cloth..... 1 50

Digitized by Google

DUBOIS (A. J.). The New Method of Graphic Statics. With 60 illustrations. 8vo, cloth..... 1 50

EDDY (Prof. H. T.). Researches in Graphical Statics. Embracing New Constructions in Graphical Statics, a New General Method in Graphical Statics, and the Theory of Internal Stress in Graphical Statics. 8vo, cloth..... 1 50

——— Maximum Stresses under Concentrated Loads. Treated graphically. Illustrated. 8vo, cloth..... 1 50

EISSLER (M.). The Metallurgy of Gold; a Practical Treatise on the Metallurgical Treatment of Gold-Bearing Ores, including the Processes of Concentration and Chlorination, and the Assaying, Melting and Refining of Gold. Fourth Edition, revised and greatly enlarged. 187 illustrations. 12mo, cloth 5 00

——— The Metallurgy of Silver; a Practical Treatise on the Amalgamation, Roasting and Lixivation of Silver Ores, including the Assaying, Melting and Refining of Silver Bullion. 124 illustrations. Second edition, enlarged, 12mo, cloth..... 4 00

——— The Metallurgy of Argentiferous Lead; a Practical Treatise on the Smelting of Silver Lead Ores and the Refining of Lead Bullion. Including Reports on Various Smelting Establishments and Descriptions of Modern Smelting Furnaces and Plants in Europe and America. With 183 illustrations. 8vo, cloth..... 5 00

——— Cyanide Process for the Extraction of Gold and its Practical Application on the Witwatersrand Gold Fields in South Africa. Second edition. Enlarged. 8vo, cloth. Illustrations and folding plates..... 3 00

——— A Hand-book on Modern Explosives, being a Practical Treatise on the Manufacture and use of Dynamite, Gun Cotton, Nitro-Glycerine and other Explosive Compounds, including the manufacture of Collodion-Cotton, with chapters on explosives in practical application. Second edition, enlarged with 150 illustrations. 12mo, cloth..... 5 00

ELIOT (C. W.), and STORER (F. H.). A compendious Manual of Qualitative Chemical Analysis. Revised with the co-operation of the authors, by Prof. William R. Nichols. Illustrated. Nineteenth edition, newly revised by Prof. W. B, Lindsay, 12mo. cloth..... 1 25

Digitized by Google

ELLIOT (Maj. GEO. H.). European Light-House Systems. Being a Report of a Tour of Inspection made in 1873. 51 engravings and 21 woodcuts. 8vo, cloth 5 00

ELLISON, (LEWIS M.). Practical Application of the Indicator. With reference to the adjustment of Valve Gear on all styles of Engines. Second edition, revised. 8vo. cloth, 100 illustrations 2 00

EVERETT (J. D.). Elementary Text book of Physics. Illustrated. Seventh edition 12mo, cloth 1 50

EWING (Prof. A. J.). The Magnetic Induction in Iron and other metals. 159 illustrations. 8vo, cloth 4 00

FANNING (J. T.). A Practical Treatise on Hydraulic and Water-Supply Engineering. Relating to the Hydrology, Hydro-dynamics, and Practical Construction of Water-Works in North America. 180 illustrations. 8vo, cloth. Fourteenth edition, revised, enlarged, and new tables and illustrations added. 650 pages..... 5 00

FISH (J. C. L.). Lettering of Working Drawings. Thirteen plates, with descriptive text. Oblong, 9x12½, boards..... 1 00

FISKE (Lieut. BRADLEY A., U. S. N.). Electricity in Theory and Practices or, The Elements of Electrical Engineering. Eighth edition. 8vo, cloth 2 50

FISHER (H. K. C. and DARBY, W. C.). Students' Guide to Submarine Cable Testing. 8vo, cloth..... 2 50

FISHER (W. C.). The Potentiometer and its Adjuncts. 8vo, cloth..... 2 25

FLEISCHMANN (W.). The Book of the Dairy. A Manual of the Science and Practice of Dairy Work. Translated from the German, by C. M. Aikman and R. Patrick Wright. 8vo, cloth..... 4 00

FLEMING (Prof. J. A.). The Alternate Current Transformer in Theory and Practice. Vol. 1—The Induction of Electric Currents; 611 pages. New edition. Illustrated. 8vo, cloth..... 5 00

Vol. 2. The Utilization of Induced Currents. Illustrated. 8vo, cloth 5 00

—— Electric Lamps and Electric Lighting. Being a course of four lectures delivered at the Royal Institution, April-May, 1894. 8vo, cloth, fully illustrated 3 00

Digitized by Google

FLEMING (Prof. J. A.). Electrical Laboratory Notes and Forms, Elementary and advanced. 4to, cloth, illustrated..... 5 00

FOLEY (NELSON), and THOS. PRAY, Jr. The Mechanical Engineers' Reference Book for Machine and Boiler Construction, in 2 parts. Part 1—General Engineering Data. Part 2—Boiler Construction. With fifty-one plates and numerous illustrations, specially drawn for this work. Folio, half mor. ...25 00

FORNEY (MATTHIAS N.). Catechism of the Locomotive. Second edition, revised and enlarged. Forty-sixth thousand. 8vo, cloth..... 3 50

FOSTER (Gen. J. G., U. S. A.). Submarine Blasting in Boston Harbor, Massachusetts. Removal of Tower and Corwin Rocks. Illustrated with 7 plates. 4to, cloth..... 3 50

FOSTER (H. A.). Electrical Engineers' Pocket Book. 1000 pages with the collaboration of Eminent Specialists ..... (In press)

FOSTER (JAMES). Treatise on the Evaporation on Saccharine, Chemical and other Liquids by the Multiple System in Vacuum and Open Air. Second edition. Diagrams and large plates. 8vo, cloth.... 7 50

FOWLER. Mechanical Engineers' Pocket Book for 1900..... 1 00

FOX (WM.), and C. W. THOMAS, M. E. A Practical Course in Mechanical Drawing. 12mo, cloth with plates 1 25

FRANCIS (JAS. B., C. E.). Lowell Hydraulic Experiments. Being a selection from experiments on Hydraulic Motors, on the Flow of Water over Weirs, in open Canals of uniform rectangular section, and through submerged Orifices and diverging Tubes. Made at Lowell, Mass. Fourth edition, revised and enlarged, with many new experiments, and illustrated with 23 copper-plate engravings. 4to, cloth.....15 00

FROST (GEO. H.). Engineer's Field Book. By C. S. Cross. To which are added seven chapters on Railroad Location and Construction. Fourth edition. 12mo, cloth 1 00

Digitized by Google

FULLER (GEORGE W.). Report on the Investigations into the Purification of the Ohio River Water at Louisville, Kentucky, made to the President and Directors of the Louisville Water Company. Published under agreement with the Directors. 4to, cloth. 3 full page plates.....net 10 00

GEIPEL (WM.), and KILGOUR, (M. H.) A Pocketbook of Electrical Engineering Formula. Illustrated. 18mo, morocco..... 3 00
Large paper edition, wide margins. 8vo, morcco, gilt edges..... 5 00

GERBER (NICHOLAS). Chemical and Physical Analysis of Milk, Condensed Milk and Infant's Milk-Food. 8vo, cloth..... 1 25

GIBBS (WILLIAM E.). Lighting by Acetylene, Generators, Burners and Electric Furnaces. With 66 illustrations. Second edition revised. 12mo, cloth.. 1 50

GILLMORE (GEN. Q. A.). Treatise on Limes, Hyraulic Cements, and Mortars. Papers on Practical Engineering, United States Engineer Department, No 9, containing Reports of numerous Experiments conducted in New York City during the years of 1858 to 1861, inclusive. With numerous illustrations. 8vo cloth..... 4 00

—— Practical Treatise on the Construction of Roads. Streets, and Pavements, with 70 illustrations. 12mo, cloth..... 2 00

—— Report on Strength of Building Stones in the United States, etc. 8vo, illustrated cloth..... 1 00

GOLDING (HENRY A.). The Theta-Phi Diagram. Practically applied to Steam, Gas, Oil and Air Engines. 12mo, cloth. Illustrated. .....net 1 25

GOODEVE (T. M.). A Text-Book on the Steam Engine. With a Supplement on Gas-Engines. Twelfth Edition, enlarged. 143 illustrations. 12mo, cloth... 2 00

GORDON (J. E. H.). School Electricity. Illustrations. 12mo, cloth..... 2 00

GORE (G., F. R. S.). The Art of Electrolytic Separation of Metals, etc. (Theoretical and Practical.) Illustrated. 8vo, cloth..... 3 50

—— Electro Chemistry Inorganic. Third Edition. 8vo, cloth..... 80

Digitized by Google

GOULD (E. SHERMAN). The Arithmetic of the Steam Engine. 8vo, cloth..... 1 00

GRIFFITHS (A. D., Ph. D.). A Treatise on Manures, or the Philosophy of Manuring. A Practical Hand-Book for the Agriculturist, Manufacturer and Student. 12mo, cloth..... 3 00

GROVER (FREDERICK). Practical Treatise on Modern Gas and Oil Engines. 8vo, cloth. Illustrated 2 00

GURDEN (RICHARD LLOYD). Traverse Tables: computed to 4 places Decimals for every ° of angle up to 100 of Distance. For the use of Surveyors and Engineers. New Edition. Folio, half morocco. .. 7 50

GUY ARTHUR (F.). Electric Light and Power, giving the Result of Practical Experience in Central S ation Work. 8vo, cloth. Illustrated.. ..... 2 50

HAEDER (HERMAN C. E.). A Hand book on the Steam Engine. With especial reference to small and medium sized engines. English editicn re-edited by the author from the second German edition, and translated with considerable additions and alterations by H. H. P. Powels. 12mo, cloth. Nearly 1100 illustrations..... 3 00

HALL (WM. S. Prof.). Elements of the Differential and Integral Calculus. Second edition. 8vo, cloth. Illustrated.....net 2 25

HALSEY (F. A.). Slide Valve Gears; an Explanation of the action and Construction of Plain and Cut-off Slide Valves. Illustrated. 12mo, cloth. Sixth edition..... 1 50

—— The Use of the Slide Rule. Illustrated with diagrams and folding plates. 16mo, boards..... 50

HAMILTON (W. G.). Useful Informs tion for Railway Men. Tenth Edition, revised and enlarged. 562 p.ges, pocket form. Morocco, gilt..... 2 00

HANCOCK (HERBERT). Text Book of Mechanics and Hydrostatics, with over 500 diagrams. 8vo, cloth 1 75

HARRISON (W. B.). The Mechanics' Tool Book. With Practical Rules and Suggestions for use of Machinists, Iron-Workers, and others. Illustrated with 44 engravings. 12mo, cloth..... 1 50

Digitized by Google

HASKINS (C. H.). The Galvanometer and its Uses. A Manual for Electricians and Students. Fourth edition. 12mo. cloth 1 50

HAWKE (WILLIAM H.). The Premier Cipher Telegraphic Code Containing 100,000 Words and Phrases. The most complete and most useful general code yet published. 4to, cloth 5 00

—— 100,000 Words; Supplement to the Premier Code. All the words are selected from the official vocabulary. Oblong quarto, cloth 4 20

HAWKINS (C. C.) and WALLIS (F.). The Dynamo; its Theory, Design and Manufacture. 190 illustrations, 12mo, cloth 3 00

HAY (ALFRED). Principles of Alternate-Current Working 12mo, cloth, illustrated 2 00

HEAP (Major D. P., U. S. A.). Electrical Appliances of the Present Day. Report of the Paris Electrical Exposition of 1881 250 illustrations. 8vo, cloth..... 2 00

HEAVISIDE (OLIVER). Electromagnetic Theory. 8vo, cloth, two volumes each..... 5 00

HENRICI (OLAUS). Skeleton Structures. Applied to the Building of Steel and Iron Bridges. Illustrated 1 50

HERRMANN (GUSTAV). The Graphical Statics of Mechanism. A Guide for the Use of Machinists, Architects, and Engineers; and also a Text-book for Technical Schools. Translated and annotated by A. P. Smith, M. E. 12mo, cloth, 7 folding plates. Third Edition 2 00

HERMANN (FELIX). Painting on Glass and Porcelain and Enamel Painting. On the Basis of Personal Practical Experience of the Condition of the Art up to date Translated by Charles Salter. Second greatly enlarged edition. 8vo, cloth, Illustrations, net..... 3 50

HEWSON (WM.). Principles and Practice of Embanking Lands from River Floods, as applied to the Levees of the Mississippi. 8vo, cloth..... 2 00

HILL (JOHN W.). The Purification of Public Water Supplies. Illustrated with valuable Tables, Diagrams and Cuts 8vo, cloth, 304 pages..... 3 00

—— The Interpretation of Water Analyses..(In Press)

Digitized by Google

HOBBS (W. R. P.). The Arithmetic of Electrical Measurements with numerous examples. Fully Worked, 12mo, cloth ..... .50

HOFF (WM. B., Com. U. S. Navy.). The Avoidance of Collisions at Sea. 18mo, morocco ..... .75

HOLLEY (ALEXANDER L.). Railway Practice. American and European Railway practice in the Economical Generation of Steam. 77 lithographed plates. Folio, cloth 12 00

HOLMES (A. BROMLEY). The Electric Light Popularly Explained. Fifth Edition. Illustrated. 12mo, paper ..... .40

HOPKINS (NEVIL M.). Model Engines and small Boats. New Methods of Engine and Boiler Making with a chapter on Elementary Ship Design and Construction. 12mo, cloth 1 25

HOSPITALIER (E.). Polyphased Alternating Currents. Illustrated. 8vo, cloth 1 40

HOWARD (C. R.). Earthwork Mensuration on the Basis of the Prismoidal Formulae. Containing Simple and Labor-saving Methods of obtaining Prismoidal Contents directly from End Areas. Illustrated by Examples and accompained by Plain Rules for Practical Uses. Illustrated. 8vo, cloth 1 50

HUMBER (WILLIAM, C. E.). A Handy Book for the Calculation of Strains in Girders and Similar Structures, and their Strength; Consisting of Formulae and Corresponding Diagrams, with numerous details for practical application, etc. Fourth Edition. 12mo, cloth 2 50

HURST (GEORGE H.). Colour; A Hand-book of the Theory of Colour. Containing ten coloured plates and 72 diagrams. 8vo, cloth. Illustrated. Price 2 50

—— Lubricating Oils, Fats and Greases. Their Origin, Preparation, Properties, Uses and Analysis. 313 pages, with 65 illustrations. 8vo, cloth 3 00

—— Soaps; A Practical Manual of the Manufacture of Domestic, Toilet and other Soaps. Illustrated with 66 Engravings. 8vo, cloth 5 00

Digitized by Google

HUTCHINSON (W. B.). Patents and How to Make Mo ey out of Them. Member of New York Bar. 12mo, cloth. New York, 1899 ..... 1 25

HUTTON (W. S.). Steam Boiler Construction. A Practical Hand-book for Engineers, Boiler Makers and Steam Users. Containing a large collection of rules and data relating to recent practice in the design, construction, and working of all kinds of stationary, locomotive and marine steam boilers. With upwards of 500 illustrations. Third edition. Carefully revised and much enlarged. 8vo, cloth... 6 00

—— Practica Engineer's Hand-book, Comprising a treatise on Modern Engines and Boilers, Marine, Locomotive and Stationary. Fourth edition. Carefully revised with additions. With upwards of 570 illustrations. 8vo, cloth..... 7 00

—— The Works' Manager's Hand-book of Modern Rules, Tables, and Data for Civil and Mechanical Engineers. Millwrights and Boiler Makers, etc., etc. With upwards of 150 illustrations. Fifth edition. Carefully revised, with additions. 8vo, cloth..... 6 00

INNES (CHARLES H.). Problems in Machine Design. For the Use of Students, Draughtsmen and others. 12mo, cloth..... 1 50

—— Centrifugal Pumps, Turbines and Water Motors. Including the Theory and Practice of Hydraulics. 12mo, cloth..... 1 50

ISHERWOOD (B. F.). Engineering Precedents for Steam Machinery. Arranged in the most practical and useful manner for Engineers. With illustrations. 2 vols. in 1. 8vo, cloth..... 2 50

JAMESON (CHARLES D.). Portland Cement. Its Manufacture and Use. 8vo, cloth..... 1 50

JAMIESON (ANDREW C. E.). A Text-Book on Steam and Steam Engines. Specially arranged for the use of Science and Art, City and Guilds of London Institute, and other Engineering Students. Tenth edition. Illustrated. 12mo, cloth..... 3 00

—— Elementary Manual on Steam and the Steam Engine. Specially arranged for the use of First-Year Science and Art, City and Guilds of London Institute, and other Elementary Engineering Students. Third edition. 12mo, cloth 1 40

Digitized by Google

JANNETTAZ (EDWARD). A Guide to the Determination of Rocks: being an Introduction to Lithology. Translated from the French by G. W. Plympton, Professor of Physical Science at Brooklyn Polytechnic Institute. 12mo, cloth..... 1 50

JOHNSTON, Prof. J. F. W., and CAMERON, Sir CHAS. Elements of Agricultural Chemistry and Geology. Seventeenth edition. 12mo, cloth..... 2 60

JOYNSON (F. H.). The Metals used in Construction. Iron, Steel, Bessemer Metal, etc. Illustrated. 12mo, cloth..... 75

——— Designing and Construction of Machine Gearing. Illustrated. 8vo, cloth..... 2 00

KANSAS CITY BRIDGE (THE.) With an Account of the Regimen of the Missouri River and a Description of the Methods used for Founding in that River. By O. Chanute, Chief Engineer, and George Morrison, Assistant Engineer. Illustrated with 5 lithographic views and 12 plates of plans. 4to, cloth... 6 00

KAPP (GISBERT C. E.). Electric Transmission of Energy and its Transformation, Subdivision, and Distribution. A Practical Hand-book. Fourth edition, revised. 12mo, cloth..... 3 50

——— Dynamos, Alternators and Transformers. 138 Illustrations. 12mo, cloth..... 4 00

KEMPE (H. R.). The Electrical Engineer's Pocket-Book of Modern Rules, Formulæ, Tables and Data. Illustrated. 32mo, mor. gilt..... 1 75

KENNELLY (A. E.). Theoretical Elements of Electro Dynamic Machinery. 8vo, cloth..... 1 50

KILGOUR, M. H., SWAN, H., and BIGGS, C. H. W. Electrical Distribution; its Theory and Practice. 174 Illustrations. 12mo, cloth..... 4 00

KING (W. H.). Lessons and Practical Notes on Steam. The Steam Engine, Propellers, etc., for Young Marine Engineers, Students, and others. Revised by Chief Engineer J. W. King, United States Navy. Nineteenth edition, enlarged. 8vo, cloth .. 2 00

KINGDON (J. A.). Applied Magnetism. An introduction to the Design of Electromagnetic Apparatus. 8vo, cloth..... 3 00

Digitized by Google

KIRKALDY (WM. G.). Illustrations of David Kirkaldy's System of Mechanical Testing, as Originated and Carried On by him during a Quarter of a Century. Comprising a Large Selection of Tabulated Results, showing the Strength and other Properties of Materials used in Construction, with explanatory Text and Historical Sketch. Numerous engravings and 25 lithographed plates. 4to, cloth.....20 00

KIRKWOOD (JAS. P.). Report on the Filtration of River Waters for the supply of Cities, as practised in Europe, made to the Board of Water Commissioners of the City of St. Louis. Illustrated by 30 double-plate engravings. 4to, cloth..... 7 50

LARRABEE (C. S.). Cipher and Secret Letter and Telegraphic Code, with Hog's Improvements. The most perfect Secret Code ever invented or discovered. Impossible to read without the key. 18mo, cloth 60

LAZELLE (H. M.). One Law in Nature. A New Corpuscular Theory comprehending Unity of Force, Identity of Matter, and its Multiple Atom Constitution, etc. 12mo, cloth..... 1 50

LEASK (A. RITCHIE). Breakdowns at Sea and How to Repair Them. With eighty-nine Illustrations. 8vo, cloth. Second edition..... 2 00

—— Triple and Quadruple Expansion Engines and Boilers and their Management. With fifty-nine illustrations. Third edition, revised. 12mo, cloth.. 2 00

—— Refrigerating Machinery: Its Principles and Management. With sixty-four illustrations. 12mo, cloth 2 00

LECKY (S. T. S.). "Wrinkles" in Practical Navigation. With 130 illustrations. 8vo, cloth. Ninth edition, revised..... 8 40

LEVY (C. L.). Electric Light Primer. A Simple and Comprehensive Digest of all of the most important facts connected with the running of the dynamo, and electric lights, with precautions for safety. For the use of persons whose duty it is to look after the plant. 8vo, paper..... 50

Digitized by Google

LIVACHE (ACH., Ingenieur Civil Des Mines). The Manufacture of Varnishes, Oil Crushing, Refining and Boiling and Kindred Industries. Translated from the French and greatly extended, by John Geddes McIntosh. 8vo, cloth. Illustrated.....net 5 00

LOCKE (ALFRED G., and CHARLES G.) A Practical Treatise on the Manufacture of Sulphuric Acid. With 77 Constructive Plates drawn to scale Measurements, and other Illustrations. Royal 8vo, cloth.10 00

LOCKERT (LOUIS). Petroleum Motor-Cars. 12mo, cloth 1 50

LOCKWOOD (THOS. D.). Electricity, Magnetism, and Electro-Telegraphy. A Practical Guide for Students, Operators, and Inspectors. 8vo, cloth. Third edition... ..... 2 50

——— Electrical Measurement and the Galvanometer; its Construction and Uses. Second edition. 32 illustrations. 12mo, cloth.... ..... 1 50

LODGE (OLIVER J.). Elementary Mechanics, including Hydrostatics and Pneumatics. Revised edition. 12mo, cloth..... ..... 1 50

LORING (A. E.). A Hand-book of the Electro-Magnetic Telegraph. Paper boards..... 50
Cloth. 75
Morocco..... 1 00

LUCE (Com. S. B.). Text-Book of Seamanship. The Equipping and Handling of Vessels under Sail or Steam. For the use of the U. S. Naval Academy. Revised and enlarged edition, by Lt. Wm. S. Benson. 8vo, cloth.....10 00

LUNGE (GEO.). A Theoretical and Practical Treatise on the Manufacture of Sulphuric Acid and Alkali with the Collateral Branches. Vol. I. Sulphuric Acid, Second edition, revised and enlarged. 342 illustrations. 8vo, cloth.....15 00
Vol. II. Second edition, revised and enlarged. 8vo, cloth.....16 80
Vol III. 8vo, cloth. New edition, 1896.....15 00

LUNGE. (GEO.), and HURTER, F. The Alkali Maker's Pocket-Book. Tables and Analytical Methods for Manufacturers of Sulphuric Acid, Nitric Acid, Soda, Potash and Ammonia. Second edition. 12mo, cloth 3 00

Digitized by Google

LUQUER (LEA McILVAINE, Ph. D.). Minerals in Rock Sections. The Practical Method of Identifying Minerals in Rock Sections with the microscope, Especially arranged for Students in Technical and Scientific Schools. 8vo. cloth. Illustrated..net 1 50

MACCORD (Prof. C. W.). A Practical Treatise on the Slide-Valve by Eccentrics, examining by methods the action of the Eccentric upon the Slide-Valve, and explaining the practical processes of laying out the movements, adapting the Valve for its various duties in the Steam Engine. Second edition. Illustrated. 4to, cloth..... 2 50

MAGUIRE (Capt. EDWARD, U. S. A.). The Attack and Defence of Coast Fortifications. With Maps and Numerous Illustrations. 8vo, cloth..... 2 50

MAGUIRE (WM. R.). Domestic Sanitary Drainage and Plumbing Lectures on Practical Sanitation. 332 illustrations. 8vo..... 4 00

MARKS (EDWARD C. R.). Mechanical Engineering Materials: their Properties and Treatment in Construction. 12mo, cloth. Illustrated..... 60

——— Notes on the Construction of Cranes and Lifting Machinery. 12mo, cloth..... 1 00

MARKS (G. C.). Hydraulic Machinery Employed in the Concentration and Transmission of Power. 12mo, cloth..... 1 25

MAVER (WM.). American Telegraphy: Systems, Apparatus, Operation. 450 illustrations. 8vo, cloth. 3 50

MAYER (Prof. A. M.). Lecture Notes on Physics. 8vo, cloth..... 2 00

McCULLOCH (Prof. R. S.). Elementary Treatise on the Mechanical Theory of Heat, and its application to Air and Steam Engines. 8vo, cloth..... 3 50

McNEILL (BEDFORD). McNeill's Code. Arranged to meet the requirements of Mining, Metallurgical and Civil Engineers, Directors of Mining, Smelting and other Companies, Bankers, Stock and Share Brokers, Solicitors, Accountants, Financiers, and General Merchants. Safety and Secrecy. 8vo, cloth. 6 00

Digitized by Google

No. 60.—STRENGTH OF WROUGHT-IRON BRIDGE MEMBERS. By S. W. Robinson, C.E.

No. 61.—POTABLE WATER AND METHODS OF DETECTING IMPURITIES. By M. N. Baker.

No. 62.—THE THEORY OF THE GAS-ENGINE. By Dougald Clerk. Second edition. With additional matter. Edited by F. E. Idell, M.E.

No. 63.—HOUSE DRAINAGE AND SANITARY PLUMBING. By W. P. Gerhard. Sixth edition. Revised.

No. 64.—ELECTRO-MAGNETS. By A. N. Mansfield.

No. 65.—POCKET LOGARITHMS TO FOUR PLACES OF DECIMALS.

No. 66.—DYNAMO-ELECTRIC MACHINERY. By S. P. Thompson. With notes by F. L. Pope. Third edition.

No. 67.—HYDRAULIC TABLES BASED ON "KUTTER'S FORMULA." By P. J. Flynn.

No. 68.—STEAM-HEATING. By Robert Briggs. Third edition, revised, with additions by A. R. Wolff.

No. 69.—CHEMICAL PROBLEMS. By Prof. J. C. Foye. Third edition, revised and enlarged.

No. 70.—EXPLOSIVE MATERIALS. John P. Wisser, U. S. A.

No. 71.—DYNAMIC ELECTRICITY. By John Hopkinson, J. N. Shoolbred, and R. E. Day.

No. 72.—TOPOGRAPHICAL SURVEYING. By George J. Specht, Prof. A. S. Hardy, John B. McMaster, and H. F. Walling.

No. 73.—SYMBOLIC ALGEBRA; OR, THE ALGEBRA OF ALGEBRAIC NUMBERS. By Prof. W. Cain.

No. 74.—TESTING MACHINES: THEIR HISTORY, CONSTRUCTION, AND USE. By Arthur V. Abbott.

No. 75.—RECENT PROGRESS IN DYNAMO-ELECTRIC MACHINES. Being a Supplement to Dynamo-Electric Machinery. By Prof. Sylvanus P. Thompson.

No. 76.—MODERN REPRODUCTIVE GRAPHIC PROCESSES. By Lieut. James S. Pettit, U.S.A.

No. 77.—STADIA SURVEYING. The Theory of Stadia Measurements. By Arthur Winslow.

No. 78.—THE STEAM-ENGINE INDICATOR, AND ITS USE. By W. B. Le Van.

No. 79.—THE FIGURE OF THE EARTH. By Frank C. Roberts, C.E.

No. 80.—HEALTHY FOUNDATIONS FOR HOUSES. By Glenn Brown.

Digitized by Google

No. 81.—WATER METERS: COMPARATIVE TESTS OF ACCURACY, DELIVERY, ETC. Distinctive features of the Worthington, Kennedy, Siemens, and Hesse meters. By Ross E. Browne.

No. 82—THE PRESERVATION OF TIMBER BY THE USE OF ANTISEPTICS. By Samuel Bagster Boulton, C. E.

No. 83.—MECHANICAL INTEGRATORS. By Prof. Henry S. H. SHAW, C. E.

No. 84.—FLOW OF WATER IN OPEN CHANNELS, PIPES, CONDUITS, SEWERS, ETC. With Tables. By P. J. Flynn, C. E.

No. 85.—THE LUMINIFEROUS ÆTHER. By Prof. de Volson Wood.

No. 86.—HAND-BOOK OF MINERALOGY: DETERMINATION AND DESCRIPTION OF MINERALS FOUND IN THE UNITED STATES. By Prof. J. C. Foye. Fourth edition, revised.

No. 87.—TREATISE ON THE THEORY OF THE CONSTRUCTION OF HELICOIDAL OBLIQUE ARCHES. By John L. Culley, C. E.

No. 88.—BEAMS AND GIRDERS. Practical Formulas for their Resistance. By P. H. Philbrick.

No. 89.—MODERN GUN COTTON: ITS MANUFACTURE, PROPERTIES, AND ANALYSIS. By Lieut. John P. Wisser, U. S. A.

No. 90.—ROTARY MOTION AS APPLIED TO THE GYROSCOPE. By Gen. J. G. Barnard.

No. 91.— LEVELING: BAROMETRIC TRIGONOMETRIC AND SPIRIT. By Prof. I. O. Baker.

No. 92.—PETROLEUM: ITS PRODUCTION AND USE. By Boverton Redwood, F. I. C., F. C. S.

No. 93.—RECENT PRACTICE IN THE SANITARY DRAINAGE OF BUILDINGS. With Memoranda on the Cost of Plumbing Work. Second edition, revised. By William Paul Gerhard, C. E.

No. 94.—THE TREATMENT OF SEWAGE. By Dr. C. Meymott Tidy.

No. 95.—PLATE GIRDER CONSTRUCTION. By Isami Hiroi, C. E. 2d edition, revised and enlarged.

No. 96.—ALTERNATE CURRENT MACHINERY. By Gisbert Kapp, Assoc. M. Inst., C. E.

No. 97.— THE DISPOSAL OF HOUSEHOLD WASTES. By W. Paul Gerhard, Sanitary Engineer.

No. 98.—PRACTICAL DYNAMO BUILDING FOR AMATEURS. HOW TO WIND FOR ANY OUTPUT. By Frederick Walker. Fully illustrated.

No. 99—TRIPLE - EXPANSION ENGINES AND ENGINE TRIALS. By Prof. Osborne Reynolds. Edited, with notes, etc., by F. E. Idell, M. E.

Digitized by Google

No. 100.—HOW TO BECOME AN ENGINEER, or the Theoretical and Practical Training necessary in fitting for the duties of the Civil Engineer. By Prof. Geo. W. Plympton.

No. 101.—THE SEXTANT, and other Reflecting Mathematical Instruments. With Practical Hints for their adjustment and use. By F. R. Brainard, U. S. Navy.

No. 102.—THE GALVANIC CIRCUIT INVESTIGATED MATHEMATICALLY. By Dr. G. S. Ohm, Berlin, 1827. Translated by William Francis. With Preface and Notes by the Editor, Thomas D. Lockwood, M.I.E.E.

No. 103.—THE MICROSCOPICAL EXAMINATION OF POTABLE WATER. With Diagrams. By Geo. W. Rafter.

No. 104.—VAN NOSTRAND'S TABLE BOOK FOR CIVIL AND MECHANICAL ENGINEERS. Compiled by Prof. Geo. W. Plympton.

No. 105.—DETERMINANTS. An Introduction to the Study of, with Examples and Applications. By Prof. G. A. Miller.

No. 106.—COMPRESSED AIR. Experiments upon the Transmission of Power by Compressed Air in Paris. (Popp's System.) By Prof. A. B. W. Kennedy. The Transmission and Distribution of Power from Central Stations by Compressed Air. By Prof. W. C. Unwin.

No. 107.—A GRAPHICAL METHOD FOR SWING-BRIDGES. A Rational and Easy Graphical Analysis of the Stresses in Ordinary Swing-Bridges. With an Introduction on the General Theory of Graphical Statics. By Benjamin F. La Rue. 4 Plates.

No. 108.—SLIDE VALVE DIAGRAMS. A French Method for Constructing Slide Valve Diagrams. By Lloyd Bankson, B.S., Assistant Naval Constructor, U. S. Navy. 8 Folding Plates.

No. 109.—THE MEASUREMENT OF ELECTRIC CURRENTS. Electrical Measuring Instruments. By James Swinburne. Meters for Electrical Energy. By C. H. Wordingham. Edited, with Preface, by T. Commerford Martin. Folding Plate and numerous illustrations.

No. 110.—TRANSITION CURVES. A Field-Book for Engineers, containing Rules and Tables for Laying out Transition Curves. By Walter G. Fox, C.E.

No. 111.—GAS-LIGHTING AND GAS-FITTING. Specifications and Rules for Gas-Piping. Notes on the advantages of Gas for Cooking and Heating, and Useful Hints to Gas Consumers. Second edition, rewritten and enlarged. By Wm. Paul Gerhard, C. E.

No. 112.—A PRIMER ON THE CALCULUS. By E. Sherman Gould, M. Am. Soc. C. E.

Digitized by Google

No. 113.—PHYSICAL PROBLEMS and their Solution. By A. Bourgougnon, formerly Assistant at Bellevue Hospital.

No. 114.—MANUAL OF THE SLIDE RULE. By F. A. Halsey, of the *American Machinist.*

No. 115.—TRAVERSE TABLES showing the difference of Latitude and Departure for distances between 1 and 100 and for Angles to Quarter Degrees between 1 degree and 90 degrees. (Reprinted from Scribner's Pocket Table Book.)

No. 116.—WORM AND SPIRAL GEARING. Reprinted from "American Machinist." By F. A. Halsey.

Digitized by Google

Digitized by Google

Digitized by Google